

序号	报告编号	发布日期	结论	影像资料
1	GX-B1340/23-9-24012	2024. 5. 6	东风井2#主要通风机系统合格。	 2024.03.30
2	GX-B1343/21-9-24014	2024.5.7	1. 矿井总进风量： 1973.5m ³ /min，总回风量： 1983.4m ³ /min； 2. 主通风机风量： 2050.9m ³ /min； 3. 矿井有效风量： 1435.8m ³ /min； 4. 矿井有效风量率： 70.0%； 5. 通风机负压：588Pa； 6. 矿井通风阻力： 554.5Pa；	 2024.3.24

3	GX-B1340/23-9-24010	2024.5.7	1#主要通风机系统合格。 。	
4	GX-B1340/23-9-24011	2024.5.7	2#主要通风机系统合格。 。	


5	GX-B1340/23-9-24013	2024.5.7	1#主要通风机系统合格。 。	
6	GX-B1340/23-9-24014	2024.5.7	2#主要通风机系统合格。 。	

7	GX-B1340/23-9-24015	2024.5.7	1#主要通风机系统合格。 。	 A photograph showing four workers in safety gear (orange and red jumpsuits, hard hats) standing in front of a large, green, industrial fan system. The fan is mounted on a concrete base. The date '2024.3.29' is visible in the bottom right corner of the photo.
8	GX-B1340/23-9-24016	2024.5.7	2#主要通风机系统合格。 。	 A photograph showing four workers in safety gear (orange and red jumpsuits, hard hats) standing in front of a large, green, industrial fan system. The fan is mounted on a concrete base. The date '2024.3.29' is visible in the bottom right corner of the photo.


9	GX-B1341/21-9-24094	2024.5.8	综合判定：合格。	
10	GX-B1341/21-9-24095	2024.5.8	综合判定：合格。	

11	GX-B1341/21-9-24096	2024.5.8	综合判定：合格。		 2024-04-05	
12	GX-B1341/21-9-24097	2024.5.8	综合判定：合格。		 2024-04-05	

13	GX-B1341/21-9-24098	2024.5.8	综合判定：合格。		 2024-04-05
14	GX-B1341/21-9-24099	2024.5.8	综合判定：合格。		 2024-04-05

15	GX-B1425/23-9-24006		1. 矿井正常通风风量： 11338.8m³/min； 2. 矿井反风风量：7209.2m³/min； 3. 机站正常通风风量：-300m中段主 通风机为5307.1m³/min，-400m中段 风机组为9795.2m³/min； 4. 机站反风风量：-300m中段主通风 机为3810.2m³/min，-400m中段风机 组为7082.7m³/min； 5. 机站反风率：-300m中段主通风机 为71.79%，-400m中段风机组为 72.31%； 6. 矿井风流反向用时：7分10秒。	
16	GX-B1341/21-9-24100	2024.5.9	综合判定：合格。	

17	GX-B1341/21-9-24101	2024.5.9	综合判定：合格。	 2024.4.12
18	GX-B1343/21-9-24017	2024.5.9	1. 矿井总进风量：3777.2m³/min， 矿井总回风量：3842.7m³/min； 2. 主通风机风量：3918.6m³/min； 3. 矿井有效风量：2652.7m³/min； 4. 矿井有效风量率：67.7%； 5. 通风机负压：849Pa； 6. 矿井通风阻力：774.2Pa。	 2024.4.12

19	GX-B1370/21-9-24006	2024. 5. 9	存在问题： 1、监控系统传感器调校制度调校周期时间未及时更新； 2、一氧化碳传感器调校记录中存在误差及报警栏未填写情况。 建议： 1、加强甲烷超限断电闭锁和故障闭锁功能维护。 2、建议建立安全监控设备检修室，负责本矿安全监控设备的安装、调校、维护和简单维修工作。 除上述问题外，其余所检项目合格。	 2024-04-04
20	GX-B1370/21-9-24004	2024年5月9日	存在问题： 一氧化碳传感器调校记录表中标准气样填写错误。 建议：加强传感器日常维护及调校。 除上述问题外，其余所检项目合格。	

21	GX-B1371/21-9-24016	2024年5月8日	存在问题： 1、无声报警装置。 2、240避灾硐室温度传感器距顶板大于0.3m。 3、风速传感器报警值未根据AQ2013.1规定进行设置。 4、监测监控设备未定期进行调校。 5、处置结果未记录备案。 6、未建立台账及报表。 7、布置图未标明分站的位置。 建议：加强传感器日常维护及调校。 除上述问题外，其余所检项目合格。	 
----	---------------------	-----------	--	---

29

30

31

32

33

34

