


序号	报告编号	发布日期	结论	影像资料
63	GX-B1336/22-6-24003	2024/9/14	所检项目合格。	 A worker in a red uniform and yellow helmet is performing an inspection on a metal cabinet. The worker is holding a red tool and pointing at the cabinet. A yellow toolbox is on the floor next to the worker. The date stamp in the bottom right corner of the image is 2024 08 18.
64	GX-B1336/22-6-24004	2024/9/14	所检项目合格。	 A worker in a red uniform and yellow helmet is holding a yellow toolbox. The worker is standing in front of a metal cabinet. The date stamp in the bottom right corner of the image is 2024 08 19.

65	GX-B1337/22-6-24001~24037	2024/9/14	本次共检电流互感器37只，37只所检项目合格。	
66	GX-B1337/22-6-24038~24039	2024/9/14	本次共检电压互感器2只，2只所检项目合格。	
67	GX-B1598/24-6-24117	2024/9/18	实测钢丝绳有效截面积损失百分比最大为0.31%，小于5%为正常。	

68	GX-B1598/24-6-24118	2024/9/18	实测钢丝绳有效截面积损失百分比最大为0.31%，小于5%为正常。	 <p>2024.06.11</p>
69	GX-B1611/23-6-24004	2024/9/19	所检项目合格	 <p>2024.07.19</p>
70	GX-B1611/23-6-24005	2024/9/19	所检项目合格	 <p>2024.07.19</p>

71	GX-B1611/23-6-24006	2024/9/19	所检项目合格	 <p>2024 07 19</p>
72	GX-B1611/23-6-24007	2024/9/19	所检项目合格	 <p>2024 07 19</p>
73	GX-B1303/21-6-24030	2024/9/21	综合判定：合格。	 <p>2024 09 02</p>

74	GX-B1303/21-6-24031	2024/9/21	综合判定：合格。	 <p>2024 09 02</p>
75	GX-B1303/21-6-24032	2024/9/21	综合判定：合格。	 <p>提升机检修安全风险告知牌 2024 09 03</p>
76	GX-B1303/21-6-24033	2024/9/21	综合判定：合格。	 <p>2024 09 03</p>

77	GX-B1304/21-6-24035	2024/9/21	综合判定：合格。	
78	GX-B1305/21-6-24023	2024/9/21	综合判定：合格。	
79	GX-B1303/21-6-24034	2024/9/21	综合判定：合格。	

80	GX-B1304/21-6-24036	2024/9/21	综合判定：合格。	
81	GX-B1304/21-6-24037	2024/9/21	综合判定：合格。	
82	GX-B1304/21-6-24038	2024/9/21	综合判定：合格。	

83	GX-B1304/21-6-24039	2024/9/21	综合判定：合格。	
84	GX-B1304/21-6-24040	2024/9/20	综合判定：合格。	
85	GX-B1304/21-6-24041	2024/9/20	综合判定：合格。	

86	GX-B1305/21-6-24024	2024/9/21	综合判定：合格。	
87	GXX-B1303/21-6-24029	2024/9/21	综合判定合格	
88	GX-B304/21-6-24043	2024/9/21	综合判定合格	