


序号	报告编号	发布日期	结论	影像资料
1	GX-B1598/21-5-23026	2023/7/1	实测钢丝绳有效截面积损失百分比最大为2.68%，小于5%为正常。	
2	GX-B1598/21-5-23027	2023/7/1	实测钢丝绳有效截面积损失百分比最大为1.76%，小于5%为正常。	
3	GX-B1598/21-5-23028	2023/7/1	实测钢丝绳有效截面积损失百分比最大为3.02%，小于5%为正常。	

4	GX-B1598/21-5-23029	2023/7/1	实测钢丝绳有效截面积损失百分比最大为1.42%，小于5%为正常。			
5	GX-B1598/21-5-23030	2023/7/1	实测钢丝绳有效截面积损失百分比最大为2.00%，小于5%为正常。			
6	GX-B1598/21-5-23031	2023/7/1	实测钢丝绳有效截面积损失百分比最大为3.11%，小于5%为正常。			

7	GX-B1380/20-5-23006	2023/7/3	所检项目合格	
8	GX-B1380/20-5-23007	2023/7/3	所检项目合格	
9	GX-B1300/20-5-23013	2023. 7. 3	所检项目合格。 。	

10	GX-B1300/20-5-23014	2023. 7. 3	所检项目合格			
11	GX-B1312/20-5-23437~23440	2023/7/4	本次共检电力 变压器4台，4 台电力变压器 所检项目合格 。			
12	GX-B1321/20-5-23754~23758	2023/7/4	本次共检电力 电缆5条，5条 电力电缆所检 项目合格。			

13	GX-B1321/20-5-23759~23760	2023/7/4	本次共检电力 电缆2条，2条 电力电缆所检 项目合格。			
14	GX-B1312/20-5-23441~23447	2023/7/4	本次共检电力 变压器7台，7 台电力变压器 所检项目合格 。			
15	GX-B1312/20-5-23448~23457	2023/7/4	本次共检电力 变压器10台， 10台电力变压 器所检项目合 格。			

16	GX-B1321/20-5-23761	2023/7/4	所检项目合格。 。	
17	GX-B1424/20-5-23021	2023. 7. 3	所检项目合格	
18	GX-B1424/20-5-23022	2023. 7. 3	所检项目合格	

19	GX-B1321/20-5-23752	2023. 7. 3	所检项目合格。 。		 <p>2023. 08. 10</p>	
20	GX-B1321/20-5-23753	2023. 7. 3	所检项目合格。 。		 <p>2023/5/6</p>	