

序号	报告编号	发布日期	结论	影像资料
64	GX-B1313/21-4-24001	2024/2/7	所检项目合格。	
65	GX-B1598/21-4-24001	2024. 2. 7	实测钢丝绳有效截面积损失百分比最大为2.08%，小于5%为正常。	

66	GX-B1598/21-4-24002	2024. 2. 7	实测钢丝绳有效截面积损失百分比最大为2.65%，小于5%为正常。	
67	GX-B1598/21-4-24003	2024. 2. 7	实测钢丝绳有效截面积损失百分比最大为3.78%，小于5%为正常。	

68	GX-B1598/21-4-24004	2024. 2. 7	实测钢丝绳有效截面积损失百分比最大为3.17%，小于5%为正常。	
69	GX-B1598/21-4-24005	2024. 2. 7	实测钢丝绳有效截面积损失百分比最大为2.72%，小于5%为正常。	

70	GX-B1598/21-4-24006	2024. 2. 7	实测钢丝绳有效截面积损失百分比最大为3.04%，小于5%为正常。	
71	GX-B1451/20-4-24001~24010	2024. 2. 7	本次共检高压开关柜10台，10台所检项目合格。 。	

72	GX-B1328/20-4-24026	2024/2/7	本次共检绝缘手套2只， 2只所检项目合格。	
73	GX-B1328/20-4-24027	2024/2/7	本次共检绝缘鞋2只，2 只所检项目合格。	

74	GX-B1500/21-4-24001	2024. 2. 7	综合判定：合格。	
75	GX-B1500/21-4-24002	2024. 2. 7	综合判定：合格。	

76	GX-B1500/21-4-24003	2024. 2. 7	综合判定：合格。			
77	GX-B1309/21-4-24001	2024. 2. 7	所检项目合格。			

78	GX-B1303/21-4-24001	2024. 2. 18	综合判定：合格。	
79	GX-B1307/20-4-24001	2024. 2. 7	综合判定：合格。	

80	GX-B1307/20-4-24002	2024. 2. 7	综合判定：合格。	
81	GX-B1307/20-4-24003	2024. 2. 7	综合判定：合格。	

82	GX-B1307/20-4-24004	2024. 2. 7	综合判定：合格。	
83	GX-B1304/21-4-24001	2024. 2. 18	综合判定：合格。	

84	GX-B1380/20-4-24001	2024. 2. 19	所检项目合格	
85	GX-B1559/22-4-24001	2024. 2. 21	所检项目合格。	

86	GX-B1559/22-4-24002	2024. 2. 21	所检项目合格。
87	GX-B1559/22-4-24003	2024. 2. 21	所检项目合格。



88	GX-B1559/22-4-24004	2024. 2. 21	所检项目合格。
89	GX-B1559/22-4-24005	2024. 2. 21	所检项目合格。



90	GX-B1559/22-4-24006	2024. 2. 21	所检项目合格。
91	GX-B1559/22-4-24007	2024. 2. 21	所检项目合格。



92	GX-B1559/22-4-24008	2024. 2. 21	所检项目合格。
----	---------------------	-------------	---------

