

序号	报告编号	发布日期	结论	影像资料
1	GX-B1500/21-Z-22042	12.8	综合判定：合格	
2	GX-B1500/21-Z-22043	12.8	综合判定：合格	
3	GX-B1500/21-Z-22044	12.8	综合判定：合格	

4	GX-B1500/21-Z-22045	12.8	综合判定：合格	
5	GX-B1500/21-Z-22046	12.8	综合判定：合格	
6	GX-B1500/21-Z-22047	12.8	综合判定：合格	
7	GX-B1309/21-Z-22007	12.8	综合判定：合格	

8	GX-B1309/21-Z-22039	12.8	综合判定：合格	
9	GX-B1309/21-Z-22040	12.8	综合判定：合格	
10	GX-B1309/21-Z-22041	12.8	综合判定：合格	
11	GX-B1307 / 20-Z-22059	12.9	综合判定：合格	

12	GX-B1307 / 20-Z-22060	12.9	综合判定：合格	 2022.11.18
13	GX-B1424 / 20-Z-22018	12.9	所检项目合格	 2022.10.23
14	GX-B1424 / 20-Z-22019	12.9	所检项目合格	 2022.10.23
15	GX-B1307/20-Z-22053	12.9	综合判定：合格	 2022.11.23

16	GX-B1307/20-Z-22054	12.9	综合判定：合格	 A worker in a blue uniform and red helmet is working on a large red industrial machine. The machine has a cylindrical component and various pipes. The worker is looking at the machine. The date 2022 11 23 is visible in the bottom right corner of the photo.
17	GX-B1307/20-Z-22055	12.9	综合判定：合格	 A worker in a blue uniform and red helmet is working on a large industrial machine. The worker is kneeling and looking at the machine. The date 2022 11 23 is visible in the bottom right corner of the photo.
18	GX-B1307/20-Z-22056	12.9	综合判定：合格	 A worker in a blue uniform and red helmet is working on a large industrial machine. The worker is kneeling and looking at the machine. The date 2022 11 23 is visible in the bottom right corner of the photo.
19	GX-B1307/20-Z-22057	12.9	综合判定：合格	 A worker in a blue uniform and red helmet is working on a large industrial machine. The worker is kneeling and looking at the machine. The date 2022 11 23 is visible in the bottom right corner of the photo.

20	GX-B1307/20-Z-22058	12.9	综合判定：合格			
----	---------------------	------	---------	--	---	--