

序号	报告编号	发布日期	结论	影像资料
193	GX-B1363/22-A-23054	2023/2/27	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
194	GX-B1363/22-A-23080	2023/2/28	所检项目合格	 <p>The photograph shows two technicians in grey work jackets with a logo on the back, standing in front of a large industrial machine. The machine is blue and grey, with several yellow warning signs, including one that says '安全防火' (Safety Fire). The technicians appear to be inspecting or operating the machine. A date stamp '2023/02/27' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
195	GX-B1364/22-A-23099	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
196	GX-B1364/22-A-23100	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
197	GX-B1364/22-A-23096	2023/2/24	成束电线电缆燃烧试验不合格；其余所检项目均合格。	

序号	报告编号	发布日期	结论	影像资料
198	GX-B1364/22-A-23097	2023/2/24	所检项目合格	 <p>2023/02/18</p> <p>成东网络试验装置</p>

序号	报告编号	发布日期	结论	影像资料
199	GX-B1364/22-A-23089	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
200	GX-B1364/22-A-23090	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
201	GX-B1364/22-A-23091	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
202	GX-B1364/22-A-23092	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
203	GX-B1364/22-A-23093	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
204	GX-B1364/22-A-23094	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
205	GX-B1364/22-A-23095	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
206	GX-B1366/20-A-23013	2023/2/24	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
207	GX-B1364/22-A-23101	2023/2/24	所检项目合格	