

序号	报告编号	发布日期	结论	影像资料
586	GX-B1423/20-Y-231584	2023年3月26日	综合判定：合格	

587	GX-B1423/20-Y-231585	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

588	GX-B1423/20-Y-231586	2023年3月26日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt construction site. Two workers wearing high-visibility green vests are standing near the truck. The background shows a clear sky and some distant structures. A yellow timestamp '2023/3/8' is visible in the bottom right corner of the image.
-----	----------------------	------------	---------	--

589	GX-B1423/20-Y-231587	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

590	GX-B1423/20-Y-231588	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

591	GX-B1423/20-Y-231589	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

592	GX-B1423/20-Y-231590	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

593	GX-B1423/20-Y-231591	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

594	GX-B1423/20-Y-231592	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

595	GX-B1423/20-Y-231593	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

596	GX-B1423/20-Y-231594	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

597	GX-B1423/20-Y-231595	2023年3月26日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt road in a desert-like environment. A worker in a high-visibility vest is standing next to the truck. The truck has the number '072' on its side. The date '2023/3/6' is visible in the bottom right corner of the photo.
-----	----------------------	------------	---------	---

598	GX-B1423/20-Y-231596	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

599	GX-B1423/20-Y-231597	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

600	GX-B1423/20-Y-231598	2023年3月26日	综合判定：合格	 <p data-bbox="1666 821 1722 837">202339</p>
-----	----------------------	------------	---------	---

601	GX-B1423/20-Y-231599	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

602	GX-B1423/20-Y-231600	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

603	GX-B1423/20-Y-231601	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

604	GX-B1423/20-Y-231602	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

605	GX-B1423/20-Y-231603	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---


606	GX-B1423/20-Y-231604	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

607	GX-B1423/20-Y-231605	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

608	GX-B1423/20-Y-231606	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

609	GX-B1423/20-Y-231607	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

610	GX-B1423/20-Y-231608	2023年3月26日	综合判定：合格	
-----	----------------------	------------	---------	---

611	GX-B1547/20-Y-23058~23069	2023年3月25日	本次共检继电保护装置12台，12台继电保护装置所检项目合格。 。	
612	GX-B1547/20-Y-23070~23084	2023年3月25日	本次共检继电保护装置15台，15台继电保护装置所检项目合格。 。	

613	GX-B1547/20-Y-23085~23097	2023年3月25日	本次共检继电保护装置13台，13台继电保护装置所检项目合格。 。	
614	GX-B1547/20-Y-23098~23107	2023年3月25日	本次共检继电保护装置10台，10台继电保护装置所检项目合格。 。	

615	GX-B1547/20-Y-23108~23115	2023年3月25日	本次共检继电保护装置8台，8台继电保护装置所检项目合格。	
616	GX-B1547/20-Y-23116~23126	2023年3月25日	本次共检继电保护装置11台，11台继电保护装置所检项目合格。 。	

617	GX-B1547/20-Y-23127~23132	2023年3月25日	本次共检继电保护装置6台，6台继电保护装置所检项目合格。	
618	GX-B1547/20-Y-23133~23142	2023年3月25日	本次共检继电保护装置10台，10台继电保护装置所检项目合格。	

619	GX-B1547/20-Y-23143~23149	2023年3月25日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	 <p>2023/3/2</p>
620	GX-B1547/20-Y-23150~23157	2023年3月25日	本次共检继电保护装置8台，8台继电保护装置所检项目合格。	 <p>2023/3/3</p>

621	GX-B1547/20-Y-23158~23159	2023年3月25日	本次共检继电保护装置2台，2台继电保护装置所检项目合格。	
622	GX-B1547/20-Y-23160~23165	2023年3月25日	本次共检继电保护装置6台，6台继电保护装置所检项目合格。	

623	GX-B1547/20-Y-23166	2023年3月25日	所检项目合格。 。	
624	GX-B1547/20-Y-23167~23175	2023年3月25日	本次共检继电保护装置9台，9台继电保护装置所检项目合格。	

625	GX-B1547/20-Y-23176	2023年3月25日	所检项目合格。 。	
626	GX-B1547/20-Y-23177~23179	2023年3月25日	本次共检继电保护装置3台，3台继电保护装置所检项目合格。	

627	GX-B1547/20-Y-23180	2023年3月25日	所检项目合格。 。	
628	GX-B1547/20-Y-23181~23187	2023年3月25日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	

629	GX-B1547/20-Y-23188~23194	2023年3月25日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	 <p>2023/3/5</p>
630	GX-B1547/20-Y-23195~23201	2023年3月25日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	 <p>2023/3/6</p>

631	GX-B1547/20-Y-23202~23208	2023年3月25日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	
632	GX-B1547/20-Y-23209~23215	2023年3月25日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	

633	GX-B1547/20-Y-23216~23226	2023年3月25日	本次共检继电保护装置11台，11台继电保护装置所检项目合格。 。	
634	GX-B1495/20-Y-23495~23506	2023年3月25日	本次共检电流互感器12只，12只电流互感器所检项目合格。	

635	GX-B1495/20-Y-23507~23554	2023年3月25日	本次共检电流互感器48只，48只电流互感器所检项目合格。	
636	GX-B1495/20-Y-23555~23576	2023年3月25日	本次共检电流互感器22只，22只电流互感器所检项目合格。	

637	GX-B1495/20-Y-23577~23590	2023年3月25日	本次共检电流互感器14只，14只电流互感器所检项目合格。	
638	GX-B1495/20-Y-23591~23614	2023年3月25日	本次共检电流互感器24只，24只电流互感器所检项目合格。	

639	GX-B1495/20-Y-23615~23644	2023年3月25日	本次共检电流互感器30只，30只电流互感器所检项目合格。	
640	GX-B1495/20-Y-23645~23670	2023年3月25日	本次共检电流互感器26只，26只电流互感器所检项目合格。	

641	GX-B1495/20-Y-23671~23690	2023年3月25日	本次共检电流互感器20只，20只电流互感器所检项目合格。	
642	GX-B1495/20-Y-23691~23706	2023年3月25日	本次共检电流互感器16只，16只电流互感器所检项目合格。	

643	GX-B1495/20-Y-23707~23728	2023年3月25日	本次共检电流互感器22只，22只电流互感器所检项目合格。	 <p>2023/3/1</p>
644	GX-B1495/20-Y-23729~23740	2023年3月25日	本次共检电流互感器12只，12只电流互感器所检项目合格。	 <p>2023/3/1</p>

645	GX-B1495/20-Y-23741~23760	2023年3月25日	本次共检电流互感器20只，20只电流互感器所检项目合格。	
646	GX-B1495/20-Y-23761~23774	2023年3月25日	本次共检电流互感器14只，14只电流互感器所检项目合格。	

647	GX-B1495/20-Y-23775~23790	2023年3月25日	本次共检电流互感器16只，16只电流互感器所检项目合格。	
648	GX-B1495/20-Y-23791~23794	2023年3月25日	本次共检电流互感器4只，4只电流互感器所检项目合格。	

649	GX-B1495/20-Y-23795~23806	2023年3月25日	本次共检电流互感器12只，12只电流互感器所检项目合格。	
650	GX-B1495/20-Y-23807~23808	2023年3月25日	本次共检电流互感器2只，2只电流互感器所检项目合格。	

651	GX-B1495/20-Y-23809~23826	2023年3月25日	本次共检电流互感器18只，18只电流互感器所检项目合格。	
652	GX-B1495/20-Y-23827~23828	2023年3月25日	本次共检电流互感器2只，2只电流互感器所检项目合格。	

653	GX-B1495/20-Y-23829~23834	2023年3月25日	本次共检电流互感器6只，6只电流互感器所检项目合格。	 A photograph showing a worker in a grey uniform and red helmet working on an electrical cabinet. The worker is seen from the side, reaching into the cabinet. A yellow timestamp '2023/3/4' is visible in the bottom right corner of the image.
654	GX-B1495/20-Y-23835~23836	2023年3月25日	本次共检电流互感器2只，2只电流互感器所检项目合格。	 A photograph showing a worker in a grey uniform and red helmet working on an electrical cabinet. The worker is seen from the side, reaching into the cabinet. A yellow timestamp '2023/3/4' is visible in the bottom right corner of the image.

655	GX-B1495/20-Y-23837~23850	2023年3月25日	本次共检电流互感器14只，14只电流互感器所检项目合格。	
656	GX-B1495/20-Y-23851~23864	2023年3月25日	本次共检电流互感器14只，14只电流互感器所检项目合格。	

657	GX-B1495/20-Y-23865~23878	2023年3月25日	本次共检电流互感器14只，14只电流互感器所检项目合格。	
658	GX-B1495/20-Y-23879~23892	2023年3月25日	本次共检电流互感器14只，14只电流互感器所检项目合格。	

659	GX-B1495/20-Y-23893~23906	2023年3月25日	本次共检电流互感器14只，14只电流互感器所检项目合格。	
660	GX-B1495/20-Y-23907~23928	2023年3月25日	本次共检电流互感器22只，22只电流互感器所检项目合格。	

661	GX-B1495/20-Y-23297~23311	2023年3月25日	本次共检高压交流断路器15台，15台高压交流断路器所检项目合格。	
662	GX-B1495/20-Y-23312~23324	2023年3月25日	本次共检高压交流断路器13台，13台高压交流断路器所检项目合格。	

663	GX-B1495/20-Y-23325~23334	2023年3月25日	本次共检高压交流断路器10台，10台高压交流断路器所检项目合格。	
664	GX-B1495/20-Y-23335~23342	2023年3月25日	本次共检高压交流断路器8台，8台高压交流断路器所检项目合格。	

665	GX-B1495/20-Y-23343~23353	2023年3月25日	本次共检高压交流断路器11台，11台高压交流断路器所检项目合格。	
666	GX-B1495/20-Y-23354~23359	2023年3月25日	本次共检高压交流断路器6台，6台高压交流断路器所检项目合格。	

667	GX-B1495/20-Y-23360~23369	2023年3月25日	本次共检高压交流断路器10台，10台高压交流断路器所检项目合格。	
668	GX-B1495/20-Y-23370~23376	2023年3月25日	本次共检高压交流断路器7台，7台高压交流断路器所检项目合格。	

669	GX-B1495/20-Y-23377~23384	2023年3月25日	本次共检高压交流断路器8台，8台高压交流断路器所检项目合格。 。	
670	GX-B1495/20-Y-23385~23386	2023年3月25日	本次共检高压交流断路器2台，2台高压交流断路器所检项目合格。 。	

671	GX-B1495/20-Y-23387~23392	2023年3月25日	本次共检高压交流断路器6台，6台高压交流断路器所检项目合格。 。	
672	GX-B1495/20-Y-23393	2023年3月25日	所检项目合格。	

673	GX-B1495/20-Y-23394~23402	2023年3月25日	本次共检高压交流断路器9台，9台高压交流断路器所检项目合格。 。	
674	GX-B1495/20-Y-23403	2023年3月25日	所检项目合格。	

675	GX-B1495/20-Y-23404~23406	2023年3月25日	<p>本次共检高压交流断路器3台，3台高压交流断路器所检项目合格。</p> <p>。</p>	
676	GX-B1495/20-Y-23407	2023年3月25日	所检项目合格。	

677	GX-B1495/20-Y-23408~23414	2023年3月25日	本次共检高压交流断路器7台，7台高压交流断路器所检项目合格。 。	
678	GX-B1495/20-Y-23415~23421	2023年3月25日	本次共检高压交流断路器7台，7台高压交流断路器所检项目合格。 。	

679	GX-B1495/20-Y-23422~23428	2023年3月25日	本次共检高压交流断路器7台，7台高压交流断路器所检项目合格。 。	
680	GX-B1495/20-Y-23429~23435	2023年3月25日	本次共检高压交流断路器7台，7台高压交流断路器所检项目合格。 。	

681	GX-B1495/20-Y-23436~23442	2023年3月25日	本次共检高压交流断路器7台，7台高压交流断路器所检项目合格。 。	 <p>2023/3/7</p>
682	GX-B1495/20-Y-23443~23453	2023年3月25日	本次共检高压交流断路器11台，11台高压交流断路器所检项目合格。	 <p>2023/3/7</p>