

序号	报告编号	发布日期	结论	影像资料
1007	GX-B1354/20-Y-23004	2023年3月31日	电网接地电容 电流符合规定。 。	 <p>2023/3/12</p>
1008	GX-B1495/20-Y-23929~23931	2023年3月30日	本次共检高压 交流断路器3 台，3台高压 交流断路器所 检项目合格。	 <p>2023/3/12</p>

1009	GX-B1495/20-Y-23932~23933	2023年3月30日	本次共检高压交流断路器2台，2台高压交流断路器所检项目合格。	
1010	GX-B1547/20-Y-23227~23230	2023年3月30日	本次共检继电保护装置4台，4台继电保护装置所检项目合格。	

1011	GX-B1547/20-Y-23231~23233	2023年3月31日	本次共检继电保护装置 3台，3台继电保护装置所检项目合格。	 <p>A photograph showing a worker in a red hard hat and grey jacket working on a control panel with many wires. The date stamp in the bottom right corner of the photo is 2023/3/31.</p>
1012	GX-B1495/20-Y-23934~23943	2023年3月26日	本次共检高压开关设备 10台，10台高压开关设备所检项目合格。	 <p>A photograph showing a worker in a red uniform and red hard hat working on a high-voltage switchgear. The date stamp in the bottom right corner of the photo is 2023/3/10.</p>

1013	GX-B1495/20-Y-23944~23952	2023年3月26日	本次共检高压开关设备9台，9台高压开关设备所检项目合格。	 <p>A photograph showing a worker in a red protective suit and helmet working on a high-voltage switchgear unit. The worker is kneeling and focused on a control panel or component. A yellow timestamp '2023/3/11' is visible in the bottom right corner of the image.</p>
1014	GX-B1495/20-Y-23953~23965	2023年3月26日	本次共检高压开关设备13台，13台高压开关设备所检项目合格。	 <p>A photograph showing two workers in a control room or office setting. One worker is seated at a desk, and the other is standing next to a large piece of equipment, possibly a high-voltage switchgear unit. A yellow timestamp '2023/3/14' is visible in the bottom right corner of the image.</p>

1015	GX-B1495/20-Y-23966	2023年3月26日	所检项目合格。	
1016	GX-B1495/20-Y-23967~23980	2023年3月30日	本次共检高压开关设备14台，14台高压开关设备所检项目合格。	

1017	GX-B1495/20-Y-23981~23993	2023年3月30日	本次共检高压开关设备13台，13台高压开关设备所检项目合格。	 <p>2023/3/13</p>
1018	GX-B1495/20-Y-23994	2023年3月30日	所检项目合格。	 <p>2023/3/13</p>

1019	GX-B1350/21-Y-23009	2023年3月30日	本次共检接地装置5处，5处接地装置所检项目合格。	 <p>A photograph showing two workers in red hard hats and dark jackets inspecting a ground device on a rooftop. One worker is kneeling and using a handheld device, while the other stands behind him. The date '2023/3/30' is visible in the bottom right corner of the photo.</p>
1020	GX-B1350/21-Y-23010	2023年3月30日	本次共检接地装置2处，2处接地装置所检项目合格。	 <p>A photograph showing a worker in a red protective suit and headlamp inspecting a ground device in a dark environment. The worker is using a handheld device. A warning sign is visible on the wall behind him. The date '2023/3/11' is visible in the bottom right corner of the photo.</p>


1021	GX-B1352/21-Y-23088~23103	2023年3月30日	本次共检矿用防爆低压交流真空馈电开关16台,16台所检项目合格。	 A worker wearing a red safety suit and a red helmet with a headlamp is inspecting a green industrial machine. The machine has a label that reads "1501-03". A yellow timestamp "2023/3/10" is visible in the bottom right corner of the photo.
1022	GX-B1352/21-Y-23104~23117	2023年3月30日	本次共检矿用防爆低压交流真空馈电开关14台,14台所检项目合格。	 A worker wearing a red safety suit and a red helmet is working on a green industrial machine. The worker is using a tool to work on the internal components of the machine. A yellow timestamp "2023/3/12" is visible in the bottom right corner of the photo.

1023	GX-B1352/21-Y-23118~23130	2023年3月30日	本次共检矿用防爆低压交流真空馈电开关13台,13台所检项目合格。	
1024	GX-B1352/21-Y-23131~23133	2023年3月30日	本次共检矿用防爆低压交流真空馈电开关3台,3台所检项目合格。	

1025	GX-B1352/21-Y-23134~23142	2023年3月30日	<p>本次共检矿用防爆低压交流真空馈电开关9台,9台所检项目合格。</p>	
1026	GX-B1329/21-Y-23009~23012	2023年3月30日	<p>本次共检氧化锌避雷器4组,4组氧化锌避雷器所检项目合格。</p>	
1027	GX-B1499/21-Y-23027	2023/3/31	<p>所检项目合格</p>	

1028	GX-B1499/21-Y-23028	2023/3/31	所检项目合格	
1029	GX-B1499/21-Y-23029	2023/3/31	所检项目合格	
1030	GX-B1499/21-Y-23030	2023/3/31	所检项目合格	
1031	GX-B1499/21-Y-23031	2023/3/31	所检项目合格	

1032	GX-B1499/21-Y-23032	2023/3/31	所检项目合格	
1033	GX-B1499/21-Y-23033	2023/3/31	所检项目合格	
1034	GX-B1499/21-Y-23034	2023/3/31	所检项目合格	
1035	GX-B1499/21-Y-23035	2023/3/31	所检项目合格	

1036	GX-B1499/21-Y-23036	2023/3/31	所检项目合格	
1037	GB-B1328/20-Y-23042	2023年3月31日	本次共检绝缘手套4只，4只绝缘手套所检项目合格。	
1038	GB-B1328/20-Y-23043	2023年3月31日	本次共检绝缘鞋4只，4只绝缘鞋所检项目合格。	

1039	GB-B1328/20-Y-23044	2023年3月31日	本次共检验 电器4支，4支 电器所检项目 合格。	
1040	GB-B1328/20-Y-23045	2023年3月31日	本次共检携带 式接地和接地 短路装置 2组，2组携 带式接地和接 地短路装置所 检项目合格。	

1041	GB-B1328/20-Y-23046	2023年3月31日	本次共检绝缘杆2组，2组绝缘杆所检项目合格。	
1042	GB-B1328/20-Y-23010	2023年3月31日	本次共检绝缘手套60只，60只绝缘手套所检项目合格。	

1043	GB-B1328/20-Y-23011	2023年3月31日	本次共检绝缘鞋50只，50只绝缘鞋所检项目合格。	
1044	GB-B1328/20-Y-23012	2023年3月31日	本次共检验电器22支，22支验电器所检项目合格。	

1045	GB-B1328/20-Y-23013	2023年3月31日	本次共检便携式接地和接地短路装置40组，40组便携式接地和接地短路装置所检项目合格。	
1046	GB-B1328/20-Y-23014	2023年3月31日	本次共检绝缘杆2支，2支绝缘杆所检项目合格。	

1047	GX-B1521/20-Y-23051	2023年3月31日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
1048	GX-B1521/20-Y-23052	2023年3月31日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

1049	GX-B1521/20-Y-23053	2023年3月31日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
1050	GX-B1521/20-Y-23054	2023年3月31日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

1051	GX-B1521/20-Y-23055	2023年3月31日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
1052	GX-B1521/20-Y-23056	2023年3月31日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

1053	GX-B1521/20-Y-23057	2023年3月31日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
1054	GX-B1521/20-Y-23058	2023年3月31日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

1055	GX-B1521/20-Y-23059	2023年3月31日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
1056	GX-B1521/20-Y-23060	2023年3月31日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

1057	GX-B1521/20-Y-23061	2023年3月31日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
1058	GX-B1521/20-Y-23062	2023年3月31日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

1059	GX-B1521/20-Y-23063	2023年3月31日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
1060	GX-B1521/20-Y-23064	2023年3月31日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

1061	GX-B1423/20-Y-231845	2023年3月31日	综合判定：合格	 <p>A yellow Weichai dump truck with license plate number 08 is parked on a dirt surface. Two workers wearing high-visibility vests and hard hats are standing in front of the truck. The date 2023/3/15 is visible in the bottom right corner of the photo.</p>
1062	GX-B1423/20-Y-231846	2023年3月31日	综合判定：合格	 <p>A yellow Weichai dump truck with license plate number 07 is parked on a dirt surface. Two workers wearing high-visibility vests and hard hats are standing in front of the truck. The date 2023/3/15 is visible in the bottom right corner of the photo.</p>

1063	GX-B1423/20-Y-231847	2023年3月31日	综合判定：合格	
1064	GX-B1423/20-Y-231848	2023年3月31日	综合判定：合格	

1065	GX-B1423/20-Y-231849	2023年3月31日	综合判定：合格	
1066	GX-B1423/20-Y-231850	2023年3月31日	综合判定：合格	

1067	GX-B1423/20-Y-231851	2023年3月31日	综合判定：合格	
1068	GX-B1423/20-Y-231852	2023年3月31日	综合判定：合格	

1069	GX-B1423/20-Y-231853	2023年3月31日	综合判定：合格	 A yellow dump truck with the number 58 on its side, parked on a dirt surface. Two workers in high-visibility vests are standing in front of the truck. A date stamp '2023/3/15' is visible in the bottom right corner of the photo.
1070	GX-B1423/20-Y-231855	2023年3月31日	综合判定：合格	 A yellow dump truck with the number 60 on its side, parked on a dirt surface. Two workers in high-visibility vests are standing in front of the truck. A date stamp '2023/3/30' is visible in the bottom right corner of the photo.

1071	GX-B1423/20-Y-231856	2023年3月31日	综合判定：合格	 A yellow dump truck with the number 39 on its side. Two people are standing in front of it for scale. The truck has '同力重工' (Tongli Heavy Industry) written on the top of the dump body. A timestamp '2023/3/30' is visible in the bottom right corner of the photo.
1072	GX-B1423/20-Y-231857	2023年3月31日	综合判定：合格	 A yellow dump truck with the number 61 on its side. Two people are standing in front of it for scale. The truck has '同力重工' (Tongli Heavy Industry) written on the top of the dump body. A timestamp '2023/3/30' is visible in the bottom right corner of the photo.

1073	GX-B1423/20-Y-231858	2023年3月31日	综合判定：合格	
1074	GX-B1423/20-Y-231859	2023年3月31日	综合判定：合格	