

序号	报告编号	发布日期	结论	影像资料
88	GX-B1363/22-A-23278	2023/7/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
89	GX-B1363/22-A-23283	2023/7/10	所检项目合格。	 A photograph showing two workers in white uniforms inspecting a large industrial furnace or boiler. One worker is wearing a blue glove. The date 2023/06/21 is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
90	GX-B1363/22-A-23282	2023/7/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
91	GX-B1363/22-A-23260	2023/7/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
92	GX-B1367/22-A-23074	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
93	GX-B1367/22-A-23073	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
94	GX-B1367/22-A-23072	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
95	GX-B1367/22-A-23071	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
96	GX-B1367/22-A-23070	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
97	GX-B1367/22-A-23069	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
98	GX-B1367/22-A-23068	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
99	GX-B1367/22-A-23067	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
100	GX-B1367/22-A-23066	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
101	GX-B1367/22-A-23065	2023/7/7	阻燃性不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
102	GX-B1367/22-A-23064	2023/7/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
103	GX-B1363/22-A-23266	2023/7/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
104	GX-B1367/22-A-23075	2023/7/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
105	GX-B1363/22-A-23310	2023/7/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
106	GX-B1364/22-A-23417	2023/7/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
107	GX-B1458/22-A-23003	2023/7/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
108	GX-B1365/20-A-23040	2023/7/12	所检项目全部合格。	 <p>2023/05/31</p>

序号	报告编号	发布日期	结论	影像资料
109	GX-B1366/20-A-23057	2023/7/12	所检项目全部合格。	 <p>The photograph captures two technicians in white lab coats working with a large industrial testing machine. One technician is positioned at the control panel, which features a prominent circular dial with a red border. The other technician is standing to the right, adjusting a component of the machine's frame. A date stamp '2023/05/31' is located in the bottom right corner of the image. The machine has a green safety cage and a warning sign with Chinese text. The background shows a plain wall and some overhead piping.</p>

序号	报告编号	发布日期	结论	影像资料
110	GX-B1364/22-A-23559	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
111	GX-B1363/22-A-23317	2023/7/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
112	GX-B1364/22-A-23599	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
113	GX-B1364/22-A-23598	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
114	GX-B1364/22-A-23578	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
115	GX-B1364/22-A-23587	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
116	GX-B1364/22-A-23597	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
117	GX-B1364/22-A-23591	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
118	GX-B1364/22-A-23592	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
119	GX-B1364/22-A-23593	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
120	GX-B1364/22-A-23594	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
121	GX-B1364/22-A-23596	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
122	GX-B1364/22-A-23595	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
123	GX-B1364/22-A-23586	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
124	GX-B1364/22-A-23588	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
125	GX-B1364/22-A-23589	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
126	GX-B1364/22-A-23590	2023/7/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
127	GX-B1508/22-A-23001	2023/7/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
128	GX-B1363/22-A-23315	2023/7/20	所检项目合格。	 A photograph showing two male technicians in light blue work shirts and gloves inspecting a large, rusted industrial furnace. The furnace has a tall, white, cylindrical chimney pipe extending from its top. One technician is on the left, looking at the furnace, while the other is on the right, wearing glasses and gloves, and appears to be adjusting or inspecting a panel on the furnace. A date stamp '2023/07/16' is visible in the bottom right corner of the photo. The background shows a plain white wall and a window with a red frame.

序号	报告编号	发布日期	结论	影像资料
129	GX-B1363/22-A-23316	2023/7/20	所检项目合格。	 A photograph showing two technicians in light blue work shirts and blue gloves inspecting a large, rusted industrial furnace. The furnace has a tall, cylindrical chimney on top. One technician is on the left, looking into the furnace's opening, while the other is on the right, holding a tool. The scene is indoors, with a window in the background showing greenery outside. A date stamp '2023/07/16' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
130	GX-B1363/22-A-23301	2023/7/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
131	GX-B1366/20-A-23080	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
132	GX-B1366/20-A-23076	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
133	GX-B1365/20-A-23051	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
134	GX-B1365/20-A-23050	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
135	GX-B1366/20-A-23073	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
136	GX-B1365/20-A-23049	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
137	GX-B1366/20-A-23077	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
138	GX-B1366/20-A-23079	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
139	GX-B1366/20-A-23078	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
140	GX-B1365/20-A-23052	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
141	GX-B1366/20-A-23074	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
142	GX-B1366/20-A-23075	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
143	GX-B1365/20-A-23048	2023/7/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
144	GX-B1366/20-A-23072	2023/7/18	所检项目全部合格。	