

序号	报告编号	发布日期	结论	影像资料
419	GX-B1423/20-Y-235504	2023年10月23日	综合判定：合格	
420	GX-B1423/20-Y-235505	2023年10月23日	综合判定：合格	

421	GX-B1423/20-Y-235506	2023年10月23日	综合判定：合格	 A yellow MT100 dump truck is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck's bed is slightly raised. A yellow timestamp '2023-10-7' is visible in the bottom right corner of the photo.
422	GX-B1423/20-Y-235507	2023年10月23日	综合判定：合格	 A yellow MT100 dump truck is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck's bed is slightly raised. A yellow timestamp '2023-10-7' is visible in the bottom right corner of the photo.

423	GX-B1423/20-Y-235508	2023年10月23日	综合判定：合格	 A yellow MT10B dump truck with the number 77 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/10/7 is visible in the bottom right corner of the image.
424	GX-B1423/20-Y-235509	2023年10月23日	综合判定：合格	 A yellow MT10B dump truck with the number 59 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/10/7 is visible in the bottom right corner of the image.

425	GX-B1423/20-Y-235510	2023年10月23日	综合判定：合格	
426	GX-B1423/20-Y-235511	2023年10月23日	综合判定：合格	

427	GX-B1423/20-Y-235512	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 57 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. A date stamp '2023/10/7' is visible in the bottom right corner of the photo.
428	GX-B1423/20-Y-235513	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 63 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. A date stamp '2023/10/7' is visible in the bottom right corner of the photo.

429	GX-B1423/20-Y-235514	2023年10月23日	综合判定：合格	 A yellow MT106 dump truck with the number 67 on its side. Two workers in high-visibility vests are standing in front of it. The date 2023/10/7 is visible in the bottom right corner of the photo.
430	GX-B1423/20-Y-235515	2023年10月23日	综合判定：合格	 A yellow MT106 dump truck with the number 69 on its side. Two workers in high-visibility vests are standing in front of it. The date 2023/10/7 is visible in the bottom right corner of the photo.

431	GX-B1423/20-Y-235516	2023年10月23日	综合判定：合格	 A yellow MT106 dump truck with the number 70 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/10/17 is visible in the bottom right corner of the photo.
432	GX-B1423/20-Y-235517	2023年10月23日	综合判定：合格	 A yellow MT106 dump truck with the number 58 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/10/17 is visible in the bottom right corner of the photo.

433	GX-B1423/20-Y-235518	2023年10月23日	综合判定：合格	 A yellow MT105 dump truck with the number 66 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/10/7 is visible in the bottom right corner of the photo.
434	GX-B1423/20-Y-235519	2023年10月23日	综合判定：合格	 A yellow MT105 dump truck with the number 76 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/10/7 is visible in the bottom right corner of the photo.

435	GX-B1423/20-Y-235520	2023年10月23日	综合判定：合格	 A yellow MT100B dump truck with the number 56 on its side, parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023-10-7' is visible in the bottom right corner of the photo.
436	GX-B1423/20-Y-235521	2023年10月23日	综合判定：合格	 A yellow MT100B dump truck with the number 60 on its side, parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023-10-7' is visible in the bottom right corner of the photo.

437	GX-B1423/20-Y-235522	2023年10月23日	综合判定：合格	
438	GX-B1423/20-Y-235523	2023年10月23日	综合判定：合格	

439	GX-B1423/20-Y-235524	2023年10月23日	综合判定：合格	
440	GX-B1423/20-Y-235525	2023年10月23日	综合判定：合格	

441	GX-B1423/20-Y-235526	2023年10月23日	综合判定：合格	
442	GX-B1423/20-Y-235527	2023年10月23日	综合判定：合格	

443	GX-B1423/20-Y-235528	2023年10月23日	综合判定：合格	
444	GX-B1423/20-Y-235529	2023年10月23日	综合判定：合格	

445	GX-B1423/20-Y-235530	2023年10月23日	综合判定：合格	
446	GX-B1423/20-Y-235531	2023年10月23日	综合判定：合格	

447	GX-B1423/20-Y-235532	2023年10月23日	综合判定：合格	 A photograph of a yellow SANY SKT1155 dump truck with the number 25 on its side. Two workers in high-visibility vests are standing in front of the truck. The date 2023/10/8 is visible in the bottom right corner of the image.
448	GX-B1423/20-Y-235533	2023年10月23日	综合判定：合格	 A photograph of a yellow SANY SKT1155 dump truck with the number 27 on its side. Two workers in high-visibility vests are standing in front of the truck. The date 2023/10/8 is visible in the bottom right corner of the image.

449	GX-B1423/20-Y-235534	2023年10月23日	综合判定：合格	
450	GX-B1423/20-Y-235535	2023年10月23日	综合判定：合格	

451	GX-B1423/20-Y-235536	2023年10月23日	综合判定：合格	
452	GX-B1423/20-Y-235537	2023年10月23日	综合判定：合格	

453	GX-B1423/20-Y-235538	2023年10月23日	综合判定：合格	 A photograph of a yellow SANY SKT1155 dump truck with the number 51 on its side. Two workers in high-visibility vests are standing in front of the truck on a gravel surface. A yellow timestamp '2023/10/23' is visible in the bottom right corner of the image.
454	GX-B1423/20-Y-235539	2023年10月23日	综合判定：合格	 A photograph of a yellow SANY SKT1155 dump truck with the number 33 on its side. Two workers in high-visibility vests are standing in front of the truck on a gravel surface. A yellow timestamp '2023/10/23' is visible in the bottom right corner of the image.

455	GX-B1423/20-Y-235540	2023年10月23日	综合判定：合格	
456	GX-B1423/20-Y-235541	2023年10月23日	综合判定：合格	

457	GX-B1423/20-Y-235542	2023年10月23日	综合判定：合格	
458	GX-B1423/20-Y-235543	2023年10月23日	综合判定：合格	

459	GX-B1423/20-Y-235544	2023年10月23日	综合判定：合格	 A yellow PX105AT truck with the number 17 on its side, parked on a dirt surface. Two workers in high-visibility vests are standing near the truck. The date 2023/10/9 is visible in the bottom right corner of the photo.
460	GX-B1423/20-Y-235545	2023年10月23日	综合判定：合格	 A yellow PX105AT truck with the number 19 on its side, parked on a dirt surface. Two workers in high-visibility vests are standing near the truck. The date 2023/10/9 is visible in the bottom right corner of the photo.

461	GX-B1423/20-Y-235546	2023年10月23日	综合判定：合格	 <p>A yellow Zhenyuan PX105AT dump truck with the number 13 on its side. Two workers in high-visibility vests are standing in front of the truck. The date 2023/10/9 is visible in the bottom right corner of the photo.</p>
462	GX-B1423/20-Y-235547	2023年10月23日	综合判定：合格	 <p>A yellow Zhenyuan PX105AT dump truck with the number 21 on its side. Two workers in high-visibility vests are standing in front of the truck. The date 2023/10/9 is visible in the bottom right corner of the photo.</p>

463	GX-B1423/20-Y-235548	2023年10月23日	综合判定：合格	 A yellow PX105AT truck with '15' on the side and '蓬翔汽车' on the front. Two workers in high-visibility vests stand in front of it. A date stamp '2023/10/9' is in the bottom right corner.
464	GX-B1423/20-Y-235549	2023年10月23日	综合判定：合格	 A yellow PX105AT truck with '9' on the side and '蓬翔汽车' on the front. Two workers in high-visibility vests stand in front of it. A date stamp '2023/10/9' is in the bottom right corner.

465	GX-B1423/20-Y-235550	2023年10月23日	综合判定：合格	 A yellow PX105AT truck with the number 1 on its side, parked on a dirt surface. Two workers in high-visibility vests are standing near the truck. The date 2023/10/9 is visible in the bottom right corner of the photo.
466	GX-B1423/20-Y-235551	2023年10月23日	综合判定：合格	 A yellow PX105AT truck with the number 7 on its side, parked on a dirt surface. Two workers in high-visibility vests are standing near the truck. The date 2023/10/9 is visible in the bottom right corner of the photo.

467	GX-B1423/20-Y-235552	2023年10月23日	综合判定：合格	 A yellow PX105AT truck with the number 11 on its side, parked on a gravel surface. Two workers in high-visibility vests are standing in front of the truck. The date 2023/10/9 is visible in the bottom right corner of the photo.
468	GX-B1423/20-Y-235553	2023年10月23日	综合判定：合格	 A yellow PX105AT truck with the number 12 on its side, parked on a gravel surface. Two workers in high-visibility vests are standing in front of the truck. The date 2023/10/9 is visible in the bottom right corner of the photo.

469	GX-B1423/20-Y-235554	2023年10月23日	综合判定：合格	 <p>A yellow truck with the model 'PX105AT' and the number '6' on its side. Two workers in high-visibility vests are standing in front of the truck. The date '2023/10/9' is visible in the bottom right corner of the photo.</p>
470	GX-B1423/20-Y-235555	2023年10月23日	综合判定：合格	 <p>A yellow truck with the model 'PX105AT' and the number '16' on its side. Two workers in high-visibility vests are standing in front of the truck. The date '2023/10/9' is visible in the bottom right corner of the photo.</p>

471	GX-B1423/20-Y-235556	2023年10月23日	综合判定：合格	
472	GX-B1423/20-Y-235557	2023年10月23日	综合判定：合格	

473	GX-B1423/20-Y-235558	2023年10月23日	综合判定：合格	
474	GX-B1423/20-Y-235559	2023年10月23日	综合判定：合格	

475	GX-B1423/20-Y-235560	2023年10月23日	综合判定：合格	
476	GX-B1423/20-Y-235561	2023年10月23日	综合判定：合格	

477	GX-B1423/20-Y-235562	2023年10月23日	综合判定：合格	
478	GX-B1423/20-Y-235563	2023年10月23日	综合判定：合格	

479	GX-B1310/21-Y-23145	2023年10月23日	符合标准要求。	 A worker wearing a white jacket and a red hard hat is inspecting a large, orange industrial component. The worker is holding a device, possibly a handheld scanner or camera. The component has a circular opening with a mesh-like structure. A yellow timestamp '2023/9/28' is visible in the bottom left corner of the photo.
480	GX-B1428/21-Y-23145	2023年10月23日	无缺陷痕迹显示。	 A worker wearing a white jacket and a red hard hat is inspecting a large industrial component. The component is a large wheel with several spokes, some of which are painted pink. The worker is holding a blue device, possibly a handheld scanner or camera. A yellow timestamp '2023/9/28' is visible in the bottom left corner of the photo.

481	GX-B1423/20-Y-235737	2023年10月23日	综合判定：合格	
482	GX-B1423/20-Y-235738	2023年10月23日	综合判定：合格	

483	GX-B1423/20-Y-235739	2023年10月23日	综合判定：合格	 A yellow dump truck with the number '08' on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand near the front of the truck. A laptop and other equipment are on the ground in the foreground. A yellow timestamp '2023-10-10' is visible in the bottom right corner of the photo.
484	GX-B1423/20-Y-235740	2023年10月23日	综合判定：合格	 A yellow dump truck with the number '10' on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand near the front of the truck. A laptop and other equipment are on the ground in the foreground. A yellow timestamp '2023-10-10' is visible in the bottom right corner of the photo.

485	GX-B1423/20-Y-235741	2023年10月23日	综合判定：合格	
486	GX-B1423/20-Y-235742	2023年10月23日	综合判定：合格	

487	GX-B1423/20-Y-235743	2023年10月23日	综合判定：合格	
488	GX-B1423/20-Y-235744	2023年10月23日	综合判定：合格	

489	GX-B1423/20-Y-235745	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 16 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The sun is visible in the background, creating a bright glow. A yellow timestamp '2023/10/10' is in the bottom right corner.
490	GX-B1423/20-Y-235746	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 38 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The sky is clear and blue. A yellow timestamp '2023/10/10' is in the bottom right corner.

491	GX-B1423/20-Y-235747	2023年10月23日	综合判定：合格	
492	GX-B1423/20-Y-235748	2023年10月23日	综合判定：合格	

493	GX-B1423/20-Y-235749	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 22 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The photo has a yellow timestamp '2023/10/19' in the bottom right corner.
494	GX-B1423/20-Y-235750	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 17 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The photo has a yellow timestamp '2023/10/19' in the bottom right corner.

495	GX-B1423/20-Y-235751	2023年10月23日	综合判定：合格	
496	GX-B1423/20-Y-235752	2023年10月23日	综合判定：合格	

497	GX-B1423/20-Y-235753	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 27 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/10/10 is visible in the bottom right corner of the photo.</p>
498	GX-B1423/20-Y-235754	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 09 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/10/10 is visible in the bottom right corner of the photo.</p>

499	GX-B1423/20-Y-235755	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 35 on its side, parked on a dirt surface. A person in a high-visibility vest is standing near the front of the truck. The date 2023-10-20 is visible in the bottom right corner of the photo.
500	GX-B1423/20-Y-235756	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 31 on its side, parked on a dirt surface. Two people in high-visibility vests are standing near the front of the truck. The date 2023-10-21 is visible in the bottom right corner of the photo.

501	GX-B1423/20-Y-235757	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 23 on its side, parked on a gravel surface. Two workers in safety gear are standing in front of it. A yellow timestamp '2023-10-11' is visible in the bottom right corner of the photo.
502	GX-B1423/20-Y-235758	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 19 on its side, parked on a gravel surface. Two workers in safety gear are standing in front of it. A yellow timestamp '2023-10-11' is visible in the bottom right corner of the photo.

503	GX-B1423/20-Y-235759	2023年10月23日	综合判定：合格	
504	GX-B1423/20-Y-235760	2023年10月23日	综合判定：合格	

505	GX-B1423/20-Y-235761	2023年10月23日	综合判定：合格	
506	GX-B1423/20-Y-235762	2023年10月23日	综合判定：合格	

507	GX-B1423/20-Y-235763	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 40 on its side is parked on a dirt surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. The date 2023/10/11 is visible in the bottom right corner of the photo.</p>
508	GX-B1423/20-Y-235764	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 36 on its side is parked on a dirt surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. The date 2023/10/11 is visible in the bottom right corner of the photo.</p>

509	GX-B1423/20-Y-235765	2023年10月23日	综合判定：合格	
510	GX-B1423/20-Y-235766	2023年10月23日	综合判定：合格	

511	GX-B1423/20-Y-235767	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 20 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/10/11 is visible in the bottom right corner of the image.
512	GX-B1423/20-Y-235768	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 30 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date 2023/10/11 is visible in the bottom right corner of the image.

513	GX-B1423/20-Y-235769	2023年10月23日	综合判定：合格	
514	GX-B1423/20-Y-235770	2023年10月23日	综合判定：合格	

515	GX-B1423/20-Y-235771	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 05 on its side is parked on a dirt surface. Two workers in orange safety gear are standing in front of the truck. The date 2023/10/11 is visible in the bottom right corner of the photo.
516	GX-B1423/20-Y-235772	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 37 on its side is parked on a dirt surface. Two workers in yellow safety gear are standing in front of the truck. The date 2023/10/11 is visible in the bottom right corner of the photo.

517	GX-B1423/20-Y-235773	2023年10月23日	综合判定：合格	
518	GX-B1423/20-Y-235774	2023年10月23日	综合判定：合格	

519	GX-B1423/20-Y-235775	2023年10月23日	综合判定：合格	
520	GX-B1423/20-Y-235776	2023年10月23日	综合判定：合格	

521	GX-B1423/20-Y-235777	2023年10月23日	综合判定：合格	
522	GX-B1423/20-Y-235778	2023年10月23日	综合判定：合格	

523	GX-B1423/20-Y-235779	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 78 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/10/12' is visible in the bottom right corner of the photo.</p>
524	GX-B1423/20-Y-235780	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 79 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/10/12' is visible in the bottom right corner of the photo.</p>

525	GX-B1423/20-Y-235781	2023年10月23日	综合判定：合格	
526	GX-B1423/20-Y-235782	2023年10月23日	综合判定：合格	

527	GX-B1423/20-Y-235783	2023年10月23日	综合判定：合格	
528	GX-B1423/20-Y-235784	2023年10月23日	综合判定：合格	

529	GX-B1423/20-Y-235785	2023年10月23日	综合判定：合格	
530	GX-B1423/20-Y-235786	2023年10月23日	综合判定：合格	

531	GX-B1423/20-Y-235787	2023年10月23日	综合判定：合格	
532	GX-B1423/20-Y-235788	2023年10月23日	综合判定：合格	

533	GX-B1423/20-Y-235789	2023年10月23日	综合判定：合格	
534	GX-B1423/20-Y-235790	2023年10月23日	综合判定：合格	

535	GX-B1423/20-Y-235791	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 88 on its side and '蓬翔汽车 PX105AT' on the body. Two workers in high-visibility vests are standing in front of the truck. The truck is parked on a gravel surface. A yellow timestamp '2023-10-12' is visible in the bottom right corner of the photo.
536	GX-B1423/20-Y-235792	2023年10月23日	综合判定：合格	 A yellow dump truck with the number 97 on its side and '蓬翔汽车 PX105AT' on the body. Two workers in high-visibility vests are standing in front of the truck. The truck is parked on a gravel surface. A yellow timestamp '2023-10-12' is visible in the bottom right corner of the photo.

537	GX-B1423/20-Y-235793	2023年10月23日	综合判定：合格	
538	GX-B1423/20-Y-235794	2023年10月23日	综合判定：合格	

539	GX-B1423/20-Y-235795	2023年10月23日	综合判定：合格	
540	GX-B1423/20-Y-235796	2023年10月23日	综合判定：合格	

541	GX-B1423/20-Y-235797	2023年10月23日	综合判定：合格	
542	GX-B1423/20-Y-235798	2023年10月23日	综合判定：合格	

543	GX-B1423/20-Y-235799	2023年10月23日	综合判定：合格	
544	GX-B1423/20-Y-235800	2023年10月23日	综合判定：合格	

545	GX-B1423/20-Y-235801	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 45 on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck has '陕汽汽车 PX100A' written on its side. A yellow timestamp '2023/10/13' is visible in the bottom right corner of the photo.</p>
546	GX-B1423/20-Y-235802	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 47 on its side is parked on a gravel surface. Three workers in high-visibility vests and hard hats are standing in front of the truck. The truck has '陕汽汽车 PX100A' written on its side. A yellow timestamp '2023/10/13' is visible in the bottom right corner of the photo.</p>

547	GX-B1423/20-Y-235803	2023年10月23日	综合判定：合格	
548	GX-B1423/20-Y-235804	2023年10月23日	综合判定：合格	

549	GX-B1423/20-Y-235805	2023年10月23日	综合判定：合格	
550	GX-B1423/20-Y-235806	2023年10月23日	综合判定：合格	

551	GX-B1423/20-Y-235807	2023年10月23日	综合判定：合格	 A yellow dump truck with the model name 'PX105AT' and '57' on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date '2023/10/13' is visible in the bottom right corner of the photo.
552	GX-B1423/20-Y-235808	2023年10月23日	综合判定：合格	 A yellow dump truck with the model name 'PX105AT' and '51' on its side is parked on a gravel surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The date '2023/10/13' is visible in the bottom right corner of the photo.

553	GX-B1423/20-Y-235809	2023年10月23日	综合判定：合格	
554	GX-B1423/20-Y-235810	2023年10月23日	综合判定：合格	

555	GX-B1423/20-Y-235811	2023年10月23日	综合判定：合格	
556	GX-B1423/20-Y-235812	2023年10月23日	综合判定：合格	

557	GX-B1423/20-Y-235813	2023年10月23日	综合判定：合格	
558	GX-B1423/20-Y-235814	2023年10月23日	综合判定：合格	

559	GX-B1423/20-Y-235815	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 49 on its side is parked on a gravel surface. Two workers in high-visibility safety gear are standing in front of the truck. The truck has '陕汽重卡' (Shaanxi Heavy Duty Truck) and '陕汽重卡 SHANSHI' written on its side. A yellow timestamp '2023/10/14' is visible in the bottom right corner of the image.</p>
560	GX-B1423/20-Y-235816	2023年10月23日	综合判定：合格	 <p>A yellow dump truck with the number 95 on its side is parked on a gravel surface. Two workers in high-visibility safety gear are standing in front of the truck. The truck has '陕汽重卡' (Shaanxi Heavy Duty Truck) and '陕汽重卡 SHANSHI' written on its side. A yellow timestamp '2023/10/14' is visible in the bottom right corner of the image.</p>

561	GX-B1423/20-Y-235817	2023年10月23日	综合判定：合格	
562	GX-B1423/20-Y-235818	2023年10月23日	综合判定：合格	

563	GX-B1423/20-Y-235819	2023年10月23日	综合判定：合格	 A yellow dump truck with a blue number '53' on the side and '蓬勃汽车 PX105AT' written on the body. Two workers in high-visibility vests and hard hats stand in front of the truck. The date '2023-10-14' is visible in the bottom right corner of the photo.
564	GX-B1423/20-Y-235820	GX-B1423/20-Y-235820	综合判定：合格	 A yellow dump truck with a blue number '63' on the side and '蓬勃汽车 PX105AT' written on the body. Two workers in high-visibility vests and hard hats stand in front of the truck. The date '2023-10-14' is visible in the bottom right corner of the photo.

565	GX-B1423/20-Y-235821	2023年10月23日	综合判定：合格	
566	GX-B1423/20-Y-235822	2023年10月23日	综合判定：合格	