


序号	报告编号	发布日期	结论	影像资料
790	GX-B1563/21-Y-23035	2023年10月30日	所检项目合格。	
791	GX-B1521/20-Y-23618	2023年10月30日	所检项目合格。	

792	GX-B1521/20-Y-23619	2023年10月30日	所检项目合格。	
793	GX-B1539/22-Y-23262	2023年10月30日	所检项目合格。	

794	GX-B1539/22-Y-23263	2023年10月30日	所检项目合格。	
795	GX-B1557/22-Y-23041	2023年10月28日	所检项目合格	

796	GX-B1557/22-Y-23042	2023年10月28日	所检项目合格	
797	GX-B1557/22-Y-23044	2023年10月28日	所检项目合格	

798	GX-B1539/22-Y-23255	2023年10月30日	所检项目合格。	 A photograph of a yellow wheel loader parked on a dirt lot. Two workers, one in a grey uniform and one in a blue uniform, are standing in front of the loader. The date '2023/9/26' is visible in the bottom right corner of the image.
799	GX-B1539/22-Y-23256	2023年10月30日	所检项目合格。	 A photograph of a yellow wheel loader parked on a dirt lot. Two workers, one in a grey uniform and one in a blue uniform, are standing in front of the loader. The date '2023/9/26' is visible in the bottom right corner of the image.

800	GX-B1515/22-Y-23011	2023年10月31日	所检项目合格。	
801	GX-B1385/21-Y-23086	2023年10月30日	所检项目合格。	