

序号	报告编号	发布日期	结论	影像资料
96	GX-B1310/21-P-24002	2024. 1. 30	符合标准要求。	 A worker wearing an orange protective suit, a red helmet, and safety glasses is kneeling and operating a piece of machinery. The worker is holding a device or control panel. The background shows a metal mesh fence and some equipment. A timestamp '2024.1.12' is visible in the bottom right corner of the image.
97	GX-B1310/21-P-24003	2024. 1. 30	符合标准要求。	 A worker wearing an orange protective suit, a red helmet, and safety glasses is working on a large industrial component. The worker is holding a tool or device. The background shows a large yellow and red structure, possibly part of a machine or container. A timestamp '2024.1.12' is visible in the bottom right corner of the image.

98	GX-B1310/21-P-24004	2024. 1. 30	符合标准要求。	 <p>2024.1.12</p>
99	GX-B1310/21-P-24005	2024. 1. 30	符合标准要求。	 <p>2024.1.13</p>
100	GX-B1306/23-P-23042	2024. 1. 28	综合判定：合格	 <p>2023.12.29</p>

101	GX-B1306/23-P-23043	2024. 1. 28	综合判定：合格	
102	GX-B1306/23-P-23044	2024. 1. 28	综合判定：合格	