

序号	报告编号	发布日期	结论	影像资料
1	GX-B1309/21-1-24001	2024. 3. 4	所检项目合格	 A worker wearing an orange jumpsuit, a red helmet, and safety glasses is standing in a tunnel. He is holding a handheld device and looking at it. The tunnel has concrete walls and a green pipe running along the wall. A yellow timestamp '2024/02/19' is visible in the bottom left corner of the photo.
2	GX-B1309/21-1-24002	2024. 3. 4	所检项目合格	 A worker wearing an orange jumpsuit, a red helmet, and safety glasses is standing in a tunnel. He is holding a handheld device and looking at it. The tunnel has concrete walls and a green pipe running along the wall. A yellow timestamp '2024/02/19' is visible in the bottom left corner of the photo.

3	GX-B1383/21-1-24003	2024. 3. 4	所检项目合格	
4	GX-B1383/21-1-24004	2024. 3. 4	所检项目合格	

5	GX-B1548/20-1-24006	2024. 3. 5	所检项目合格	
---	---------------------	------------	--------	---

23045

