

序号	报告编号	发布日期	结论	影像资料
1	GX-B1361/22-A-24231	2024/3/4	合格	
2	GX-B1362/20-A-24076	2024/3/6	合格	

序号	报告编号	发布日期	结论	影像资料
3	GX-B1361/22-A-24228	2024/3/1	不合格	
4	GX-B1361/22-A-24221	2024/3/6	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
5	GX-B1361/22-A-24222	2024/3/6	所检项目合格		
6	GX-B1361/22-A-24223	2024/3/6	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
7	GX-B1361/22-A-24224	2024/3/6	所检项目合格		
8	GX-B1361/22-A-24225	2024/3/6	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
9	GX-B1361/22-A-24226	2024/3/6	所检项目合格	
10	GX-B1361/22-A-24227	2024/3/6	不合格	

序号	报告编号	发布日期	结论	影像资料
11	GX-B1361/22-A-24229	2024/3/6	所检项目合格	
12	GX-B1361/22-A-24230	2024/3/6	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
13	GX-B1362/20-A-24071	2024/3/8	合格	 A photograph showing two male workers in grey work uniforms operating a large industrial machine in a workshop. The worker on the right is in the foreground, focused on his task. The worker on the left is slightly behind him. The machine has a perforated metal tray. A yellow timestamp '2024/3/4' is visible in the bottom right corner of the image.
14	GX-B1362/20-A-24072	2024/3/8	合格	 A photograph showing two male workers in grey work uniforms operating a large industrial machine in a workshop. The worker on the right is in the foreground, focused on his task. The worker on the left is slightly behind him. The machine has a perforated metal tray. A yellow timestamp '2024/3/4' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
15	GX-B1362/20-A-24073	2024/3/8	合格	 A photograph showing two men in grey work uniforms working in a workshop. They are positioned around a large, light-colored industrial machine. One man is leaning over the machine, while the other stands beside him, looking at something. A yellow timestamp '2024/3/4' is visible in the bottom right corner of the image.
16	GX-B1362/20-A-24074	2024/3/8	合格	 A photograph showing two men in grey work uniforms working in a workshop. They are positioned around a large, light-colored industrial machine. One man is leaning over the machine, while the other stands beside him, looking at something. A yellow timestamp '2024/3/4' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
17	GX-B1362/20-A-24075	2024/3/8	合格	
18	GX-B1361/22-A-24245	2024/3/8	合格	

序号	报告编号	发布日期	结论	影像资料
19	GX-B1361/22-A-24246	2024/3/8	合格	 A photograph showing two workers in a workshop. One worker is operating a large industrial machine, possibly a lathe or mill, while the other stands nearby. The date stamp '2024/3/3' is visible in the bottom right corner of the image.
20	GX-B1361/22-A-24250	2024/3/8	合格	 A photograph showing a worker in a workshop operating a machine. The worker is wearing a light-colored jacket and gloves. The date stamp '2024/3/5' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
21	GX-B1361/22-A-24251	2024/3/8	合格	
22	GX-B1361/22-A-24252	2024/3/8	合格	

序号	报告编号	发布日期	结论	影像资料
23	GX-B1361/22-A-24253	2024/3/8	所检项目合格	