


序号	报告编号	发布日期	结论	影像资料
33	GX-B1322/21-2-24007~24008	2024. 3. 12	本次共检验电力电缆2条， 2条所检项目合格。	 2024/03/03
34	GX-B1322/21-2-24009~24015	2024. 3. 12	本次共检验电力电缆7条， 7条所检项目合格。	 2024/03/02

35	GX-B1380/20-2-24001	2024. 3. 21	所检项目合格。	
36	GX-B1517/20-2-24001	2024. 3. 22	综合判定：合格。	

37	GX-B1517/20-2-24002	2024. 3. 22	综合判定：合格。	
38	GX-B1517/20-2-24003	2024. 3. 22	综合判定：合格。	

39	GX-B1517/20-2-24004	2024. 3. 22	综合判定：合格。	
40	GX-B1517/20-2-24005	2024. 3. 22	综合判定：合格。	

41	GX-B1324/21-2-24001~24004	2024. 3. 22	本次共检三相交流电动机 4台，4台三相交流电动机所检 项目合格。	
42	GX-B1304/21-2-24002	2024. 3. 22	综合判定：合格。	

43	GX-B1304/21-2-24003	2024. 3. 22	综合判定：合格。	 A photograph showing three workers in white safety jackets and red hard hats standing in an industrial facility. They are positioned near large machinery, possibly a turbine or generator. The floor is green, and there are blue gas cylinders visible. A timestamp '2024-03-01' is visible in the bottom right corner of the image.
44	GX-B1322/21-2-24001~24006	2024. 3. 15	本次共检验电力电缆6条，6条所检项目合格。	 A photograph of a worker wearing a red hard hat, a blue face mask, and a grey safety jacket. The worker is kneeling and using a tool on a piece of equipment, possibly a cable or a component of a machine. The worker has a headlamp on their helmet. A timestamp '2024/03/03' is visible in the bottom right corner of the image.

45	GX-B1522/20-2-24001	2024/3/19	所检项目合格。	
46	GX-B1522/20-2-24002	2024/3/19	所检项目合格。	

47	GX-B1522/20-2-24003	2024/3/19	所检项目合格。	 A close-up photograph of a male worker wearing a red hard hat and safety glasses. He is dressed in a grey work uniform and is leaning over, intently reading a white document or checklist. The background shows a construction site with large orange machinery and piles of earth and rocks. A small date stamp '2024/03/07' is visible in the bottom right corner of the photo.
48	GX-B1522/20-2-24004	2024/3/19	所检项目合格。	 A photograph showing two workers on a construction site. One worker in the foreground is wearing a grey uniform and a red hard hat, gesturing towards the right. Another worker in a yellow hard hat is partially visible behind him. To the right, a large orange excavator is parked on a dirt and rock surface. The background consists of a large pile of excavated earth and rocks. A small date stamp '2024/03/07' is visible in the bottom right corner of the photo.