


序号	报告编号	发布日期	结论	影像资料
23	GX-B1313/21-4-24002	2024. 4. 22	所检项目合格。	 A photograph showing several workers in a control room or substation. They are wearing hard hats and safety gear. One worker is pointing towards a panel. The date '2024. 4. 1' is visible in the bottom right corner of the image.
24	GX-B1495/20-4-24186~24195	2024. 4. 22	玉配电装置10台，1	 A photograph showing workers in a tunnel or underground setting. They are wearing hard hats and safety gear. One worker is holding a red tool or device. The date '2024.3.5' is visible in the bottom right corner of the image.

25	GX-B1495/20-4-24196~24198	2024. 4. 22	开关柜3台, 3台所	
26	GX-B1495/20-4-24199~24206	2024. 4. 22	防爆开关8台, 8台所	
27	GX-B1495/20-4-24207~24213	2024. 4. 22	防爆开关7台, 7台所	


28	GX-B1495/20-4-24214~24223	2024. 4. 22	爆开关10台, 10台	
29	GX-B1495/20-4-24224~24234	2024. 4. 22	开关柜11台, 11台所	
30	GX-B1495/20-4-24235~24244	2024. 4. 22	开关柜10台, 10台所	

31	GX-B1495/20-4-24245~24257	2024. 4. 22	开关柜13台， 13台所	
32	GX-B1495/20-4-24258~24264	2024. 4. 22	开关柜7台， 7台所	
33	GX-B1495/20-4-24265~24272	2024. 4. 22	开关柜8台， 8台所	

34	GX-B1322/21-4-24006~24015	2024. 4. 22	本次共检电力 电缆10条，10条所 检项目合格。	
35	GX-B1451/20-4-24026~24037	2024. 2. 22	本次共检高压开 关柜12台，12台所 检项目合格。	
36	GX-B1451/20-4-24038	2024. 2. 22	所检项目合格。	

37	GX-B1328/20-4-24049	2024. 4. 22	所检项目合格。	
38	GX-B1328/20-4-24050	2024. 4. 22	本次共检验电器3支，3支所检项目合格。	
39	GX-B1328/20-4-24051	2024. 4. 22	本次共检短路接地线2套，2套所检项目合格。	

40	GX-B1422/23-4-24001	2024. 4. 24	综合判断：合格。	
41	GX-B1422/23-4-24002	2024. 4. 24	综合判断：合格。	
42	GX-B1328/20-4-24044	2024. 4. 30	本次共检绝缘手套2只，2只所检项目合格。	

43	GX-B1328/20-4-24045	2024. 4. 30	本次共检绝缘鞋2只，2只所检项目合格。	
44	GX-B1328/20-4-24046	2024. 4. 30	所检项目合格。	