

序号	报告编号	发布日期	结论	影像资料
168	GX-B1361/22-A-24504	2024/5/17	合格	
169	GX-B1362/20-A-24208	2024/5/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
170	GX-B1361/22-A-24507	2024/5/17	合格	
171	GX-B1361/22-A-24508	2024/5/17	合格	

序号	报告编号	发布日期	结论	影像资料
172	GX-B1361/22-A-24492	2024/5/22	所检项目合格	
173	GX-B1361/22-A-24500	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
174	GX-B1361/22-A-24501	2024/5/22	所检项目合格	
175	GX-B1361/22-A-24502	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
176	GX-B1361/22-A-24503	2024/5/22	所检项目合格	
177	GX-B1361/22-A-24505	2024/5/22	合格	

序号	报告编号	发布日期	结论	影像资料
178	GX-B1361/22-A-24506	2024/5/22	所检项目合格	
179	GX-B1361/22-A-24512	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
180	GX-B1361/22-A-24513	2024/5/22	所检项目合格	
181	GX-B1361/22-A-24514	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
182	GX-B1361/22-A-24515	2024/5/22	不合格	
183	GX-B1361/22-A-24519	2024/5/22	合格	

序号	报告编号	发布日期	结论	影像资料
184	GX-B1361/22-A-24520	2024/5/22	合格	
185	GX-B1361/22-A-24531	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
186	GX-B1361/22-A-24532	2024/5/22	所检项目合格	
187	GX-B1361/22-A-24533	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
188	GX-B1362/20-A-24193	2024/5/22	所检项目合格	
189	GX-B1362/20-A-24194	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
190	GX-B1362/20-A-24195	2024/5/22	所检项目合格	
191	GX-B1362/20-A-24196	2024/5/22	最小破断拉力总和 1838.31，其余所检项目合格	

序号	报告编号	发布日期	结论	影像资料
192	GX-B1362/20-A-24197	2024/5/22	最小破断拉力总和 1842.91，其余所检项目合格	
193	GX-B1362/20-A-24198	2024/5/22	最小破断拉力总和 1839.92，其余所检项目合格	

序号	报告编号	发布日期	结论	影像资料
194	GX-B1362/20-A-24199	2024/5/22	最小破断拉力总和1841.74，其余所检项目合格	
195	GX-B1362/20-A-24200	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
196	GX-B1362/20-A-24201	2024/5/22	所检项目合格		
197	GX-B1362/20-A-24202	2024/5/22	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
198	GX-B1362/20-A-24203	2024/5/22	所检项目合格	
199	GX-B1362/20-A-24204	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
200	GX-B1362/20-A-24205	2024/5/22	所检项目合格	
201	GX-B1362/20-A-24206	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
202	GX-B1362/20-A-24207	2024/5/22	所检项目合格	
203	GX-B1362/20-A-24209	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
204	GX-B1362/20-A-24210	2024/5/22	所检项目合格	
205	GX-B1362/20-A-24211	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
206	GX-B1362/20-A-24212	2024/5/22	所检项目合格	
207	GX-B1362/23-A-24213	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
208	GX-B1362/23-A-24214	2024/5/22	所检项目合格	 A photograph showing a worker in a light-colored uniform operating a lathe machine in a workshop. The machine is a large, industrial-grade lathe with a prominent tool rest and a tailstock. The worker is focused on the task, and the background shows other workshop equipment and a clean, well-lit environment. A yellow timestamp '2024/5/14' is visible in the bottom right corner of the image.
209	GX-B1362/23-A-24215	2024/5/22	合格	 A photograph showing two workers in light-colored uniforms operating a machine in a workshop. The machine appears to be a large industrial press or mill. One worker is positioned on the left, and the other is on the right, both focused on their tasks. The workshop is well-lit, and various tools and equipment are visible in the background. A yellow timestamp '2024/5/15' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
210	GX-B1362/23-A-24216	2024/5/22	所检项目合格	
211	GX-B1361/22-A-24510	2024/5/22	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
212	GX-B1361/22-A-24556	2024/5/23	所检项目合格	