


序号	报告编号	发布日期	结论	影像资料（ JPG格式 ）
1	GX-B1343/21-8-24010	2024.6.4	一区通风系统736.0Pa；三区通风系统847.0Pa；五区通风系统625.2Pa。	
2	GX-B1525/21-8-24025	2024.6.4	该局部通风机共检5项，除风量（流量）、风压（全压）不判定外，其他所检项目均合格。	

3	GX-B1525/21-8-24026	2024.6.4	该局部通风机共检5项，除风量（流量）、风压（全压）不判定外，其他所检项目均合格。	 2024.5.21
4	GX-B1525/21-8-24027	2024.6.4	该局部通风机共检5项，除风量（流量）、风压（全压）不判定外，其他所检项目均合格。	 2024.5.21
5	GX-B1525/21-8-24028	2024.6.4	该局部通风机共检5项，除风量（流量）、风压（全压）不判定外，其他所检项目均合格。	 2024.5.21

6	GX-B1525/21-8-24029	2024.6.4	该局部通风机共检5项，除风量（流量）、风压（全压）不判定外，其他所检项目均合格。	
7	GX-B1525/21-8-24030	2024.6.4	该局部通风机共检5项，除风量（流量）、风压（全压）不判定外，其他所检项目均合格。	
8	GX-B1525/21-8-24031	2024.6.4	该局部通风机共检5项，除风量（流量）、风压（全压）不判定外，其他所检项目均合格。	

9	GX-B1343/21-8-24008	2024. 6. 4	1. 矿井总进风量: 2376.6 m³/min; 2. 矿井总回风量: 2488.1 m³/min; 3. 主通风机风量: 2541.0 m³/min; 4. 矿井有效风量: 1924.0 m³/min; 5. 矿井有效风量率: 75.7%; 6. 机站风量: 三号斜井口主通风机2541.0 m³/min; 7. 机站风压: 三号斜井口主通风机1080Pa; 8. 矿井通风阻力: 955.2Pa;	A photograph showing four miners standing in a tunnel. Two are wearing orange jumpsuits and red helmets, and two are wearing blue jumpsuits and yellow helmets. They are holding tools. A green exit sign is visible in the background. The date '2024.5.4' is printed at the bottom right of the image. A photograph of three people in a meeting room. Two men and one woman are gathered around a large table, looking at a large map or blueprint. A blue banner with white Chinese text '加州... 安全生产' is visible on the wall behind them. The date '2024.5.4' is printed at the bottom right of the image.
---	---------------------	------------	--	--

