

序号	报告编号	发布日期	结论	影像资料
376	GX-B1557/22-Y-24039	2024年6月13日	所检项目合格。	
377	GX-B1557/22-Y-24040	2024年6月13日	所检项目合格。	

378	GX-B1522/20-Y-24094	2024年6月13日	所检项目合格。	
379	GX-B1522/20-Y-24094	2024年6月13日	所检项目合格。	

380	GX-B1521/20-Y-24263	2024年6月14日	所检项目合格。	 A yellow XCMG excavator is shown at a construction site. The excavator is positioned on a dirt surface, and its bucket is lowered. Two workers in safety gear are visible near the machine. The background shows a rocky hillside. A yellow date stamp '2024/5/7' is visible in the bottom right corner of the image.
381	GX-B1521/20-Y-24264	2024年6月14日	所检项目合格。	 A yellow XCMG excavator is shown at a construction site. The excavator is positioned on a dirt surface, and its bucket is lowered. Two workers in safety gear are visible near the machine. The background shows a rocky hillside. A yellow date stamp '2024/5/7' is visible in the bottom right corner of the image.

382	GX-B1521/20-Y-24265	2024年6月14日	所检项目合格。	 A photograph showing a worker in a red hard hat and safety vest operating a small yellow excavator. Another worker in a yellow hard hat and safety vest is standing nearby. The date stamp '2024/5/7' is visible in the bottom right corner.
383	GX-B1521/20-Y-24266	2024年6月14日	所检项目合格。	 A photograph of a large yellow excavator operating on a construction site. A worker in a yellow hard hat and safety vest is standing nearby. The date stamp '2024/5/7' is visible in the bottom right corner.

384	GX-B1521/20-Y-24267	2024年6月14日	所检项目合格。	 A photograph showing a person wearing a red hard hat and a light-colored uniform, operating a piece of heavy machinery from inside a cab. The person is looking down at controls. A yellow timestamp '2024/5/7' is visible in the bottom right corner of the image.
385	GX-B1521/20-Y-24268	2024年6月14日	所检项目合格。	 A photograph of a yellow excavator working on a dirt construction site. The excavator's arm is extended, and its bucket is visible. In the background, there is a large earthen wall and another piece of machinery. A yellow timestamp '2024/5/7' is visible in the bottom right corner of the image.

386	GX-B1521/20-Y-24269	2024年6月14日	所检项目合格。	
387	GX-B1521/20-Y-24270	2024年6月14日	所检项目合格。	

388	GX-B1539/22-Y-24151	2024年6月14日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface in front of a large, reddish-brown earthen wall. Two workers wearing hard hats and safety vests are standing next to the loader. A yellow date stamp '2024/5/7' is visible in the bottom right corner of the photo.
389	GX-B1539/22-Y-24152	2024年6月14日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface in front of a large, reddish-brown earthen wall. Two workers wearing hard hats and safety vests are standing next to the loader. A yellow date stamp '2024/5/7' is visible in the bottom right corner of the photo.

390	GX-B1539/22-Y-24153	2024年6月14日	所检项目合格。	
391	GX-B1539/22-Y-24154	2024年6月14日	所检项目合格。	

392	GX-B1539/22-Y-24155	2024年6月14日	所检项目合格。	
393	GX-B1539/22-Y-24156	2024年6月14日	所检项目合格。	

394	GX-B1539/22-Y-24157	2024年6月14日	所检项目合格。	
395	GX-B1521/20-Y-24434	2024年6月14日	所检项目合格。	

396	GX-B1521/20-Y-24435	2024年6月14日	所检项目合格。	
397	GX-B1521/20-Y-24436	2024年6月14日	所检项目合格。	

398	GX-B1521/20-Y-24437	2024年6月14日	所检项目合格。	 A green and black excavator is shown working on a rocky, uneven terrain. The excavator's arm is extended, and its bucket is positioned near a pile of rocks. A person in a yellow safety vest stands next to the excavator for scale. The date stamp '2024/6/27' is visible in the bottom right corner of the image.
399	GX-B1521/20-Y-24438	2024年6月14日	所检项目合格。	 A red Hitachi excavator is shown on a flat, dry dirt field. The excavator's arm is raised, and its bucket is open. A person in a yellow safety vest stands next to the excavator for scale. The date stamp '2024/6/27' is visible in the bottom right corner of the image.

400	GX-B1521/20-Y-24439	2024年6月14日	所检项目合格。	
401	GX-B1521/20-Y-24440	2024年6月14日	所检项目合格。	

402	GX-B1521/20-Y-24441	2024年6月14日	所检项目合格。	
403	GX-B1385/21-Y-24029	2024年6月17日	所检项目合格。	

404	GX-B1385/21-Y-24030	2024年6月17日	所检项目合格。	
405	GX-B1385/21-Y-24031	2024年6月17日	所检项目合格。	

406	GX-B1385/21-Y-24032	2024年6月17日	所检项目合格。	
407	GX-B1385/21-Y-24033	2024年6月17日	所检项目合格。	

408	GX-B1385/21-Y-24034	2024年6月17日	所检项目合格。	
409	GX-B1385/21-Y-24035	2024年6月17日	所检项目合格。	

410	GX-B1385/21-Y-24036	2024年6月17日	所检项目合格。	
411	GX-B1385/21-Y-24037	2024年6月17日	所检项目合格。	

412	GX-B1385/21-Y-24038	2024年6月17日	所检项目合格。	 A worker in a grey uniform and black cap is operating a blue industrial machine. The worker is holding a tool and appears to be adjusting or inspecting a part of the machine. The background shows a blue structure and some yellow safety railings. A yellow timestamp '2024/3/30' is visible in the bottom right corner of the photo.
413	GX-B1559/22-Y-24018	2024年6月13日	所检项目合格。	 Two workers in white uniforms and red hard hats are standing in front of a yellow vehicle, possibly a forklift or a small truck. They are standing on a paved surface. In the background, there is a large industrial building with many windows. A yellow timestamp '2024/5/23' is visible in the bottom right corner of the photo.

414	GX-B1521/20-Y-24449	2024年6月17日	所检项目合格。	
415	GX-B1521/20-Y-24450	2024年6月17日	所检项目合格。	

416	GX-B1521/20-Y-24451	2024年6月17日	所检项目合格。	
417	GX-B1306/23-Y-24027	2024年6月13日	综合判定：合格。	

418	GX-B1306/23-Y-24028	2024年6月13日	综合判定：合格。	 A photograph showing two workers in safety gear inspecting a piece of machinery. One worker is wearing a red hard hat and a light-colored jacket, holding a clipboard. The other worker is wearing a dark jacket and a black hard hat. They are standing next to a large, dark-colored machine with a yellow label that reads '2024/6/13'.
419	GX-B1521/20-Y-24271	所检项目合格。	2024年6月18日	 A photograph of a yellow XCMG excavator with the number '10' on its arm, parked on a dirt surface. Two workers in safety gear are standing next to the excavator. The background shows a dirt hill and a clear blue sky. A yellow label in the bottom right corner reads '2024/6/18'.

420	GX-B1521/20-Y-24272	所检项目合格。	2024年6月18日	 A yellow XCMG excavator is shown in operation on a dirt construction site. The excavator's arm is raised, and its bucket is positioned near a pile of earth. Two workers in safety gear are standing nearby. The background shows a clear sky and distant hills. A yellow timestamp '2024/5/8' is visible in the bottom right corner of the image.
421	GX-B1521/20-Y-24273	所检项目合格。	2024年6月18日	 A close-up view of a worker inside the cab of an excavator. The worker is wearing a red hard hat and a light-colored long-sleeved shirt. They are seated and looking down at a device or controls in their hands. The interior of the cab and the excavator's controls are visible. A yellow timestamp '2024/5/8' is visible in the bottom right corner of the image.

422	GX-B1521/20-Y-24274	所检项目合格。	2024年6月18日	
423	GX-B1521/20-Y-24275	所检项目合格。	2024年6月18日	

424	GX-B1521/20-Y-24276	所检项目合格。	2024年6月18日	 A yellow XCMG excavator with the number 9 on its arm is positioned on a dirt construction site. Two workers in safety gear are standing near the machine. A date stamp '2024/5/8' is visible in the bottom right corner of the photo.
425	GX-B1521/20-Y-24277	所检项目合格。	2024年6月18日	 A yellow XCMG excavator with the number 12 on its arm is positioned on a dirt construction site. Two workers in safety gear are standing near the machine. A date stamp '2024/5/8' is visible in the bottom right corner of the photo.

426	GX-B1521/20-Y-24278	所检项目合格。	2024年6月18日	 A yellow XCMG excavator with the number 13 on its arm is parked on a sandy construction site. Two workers in safety gear stand in front of it. A yellow date stamp '2024/5/8' is in the bottom right corner.
427	GX-B1521/20-Y-24279	所检项目合格。	2024年6月18日	 A yellow XCMG excavator with the number 2 on its arm is parked on a sandy construction site. Two workers in safety gear stand in front of it. A yellow date stamp '2024/5/8' is in the bottom right corner.

428	GX-B1521/20-Y-24280	所检项目合格。	2024年6月18日	 A worker wearing a red hard hat and a light blue uniform is seated inside the cab of a piece of heavy machinery, possibly a bulldozer or excavator. The worker is looking down at a device or control panel in their hands. The background shows the interior of the cab and some mechanical parts. A yellow timestamp "2024/5/8" is visible in the bottom right corner of the image.
429	GX-B1521/20-Y-24281	所检项目合格。	2024年6月18日	 A yellow XCMG excavator is parked on a dirt surface. Two workers in safety gear (hard hats and high-visibility vests) are standing next to the machine. The excavator has "XCMG" and the number "8" visible on its arm. The background shows a construction site with some earth and a cloudy sky. A yellow timestamp "2024/5/8" is visible in the bottom right corner of the image.

430	GX-B1521/20-Y-24282	所检项目合格。	2024年6月18日	 A yellow excavator with the number '6' on its arm is working on a construction site. It is positioned on a dirt surface, and its bucket is raised. In the background, there is a large pile of earth and some construction equipment. A person in a blue uniform is standing near the excavator. The date '2024/5/8' is visible in the bottom right corner of the image.
431	GX-B1521/20-Y-24283	所检项目合格。	2024年6月18日	 An orange Hitachi excavator is shown on a construction site. The excavator is positioned on a dirt surface, and its bucket is raised. In the background, there is a large pile of earth and some construction equipment. A person in a blue uniform is standing near the excavator. The date '2024/5/10' is visible in the bottom right corner of the image.

432	GX-B1521/20-Y-24284	所检项目合格。	2024年6月18日	 A photograph showing a male worker wearing a red hard hat and a light blue long-sleeved uniform shirt. He is seated inside the cab of a vehicle, possibly a truck or a piece of heavy machinery, and is looking out the window. A yellow date stamp "2024/5/10" is visible in the bottom right corner of the image.
433	GX-B1521/20-Y-24285	所检项目合格。	2024年6月18日	 A photograph of a red Hitachi excavator at a construction or mining site. The excavator is positioned on a dirt surface, and its large bucket is visible. Several workers in safety gear are standing near the machine. A yellow date stamp "2024/5/10" is visible in the bottom right corner of the image.

434	GX-B1521/20-Y-24286	所检项目合格。	2024年6月18日	
435	GX-B1521/20-Y-24287	所检项目合格。	2024年6月18日	

436	GX-B1521/20-Y-24288	所检项目合格。	2024年6月18日	
437	GX-B1521/20-Y-24289	所检项目合格。	2024年6月18日	

438	GX-B1521/20-Y-24290	所检项目合格。	2024年6月18日	
439	GX-B1521/20-Y-24291	所检项目合格。	2024年6月18日	

440	GX-B1521/20-Y-24292	所检项目合格。	2024年6月18日	
441	GX-B1539/22-Y-24158	所检项目合格。	2024年6月18日	

442	GX-B1539/22-Y-24159	所检项目合格。	2024年6月18日	 A yellow wheel loader is parked on a dirt surface. Two workers, one in a grey shirt and red helmet, and another in a blue shirt and yellow safety vest with a red helmet, are standing next to the front wheel. A yellow date stamp '2024/5/8' is in the bottom right corner.
443	GX-B1539/22-Y-24160	所检项目合格。	2024年6月18日	 A yellow wheel loader is parked on a dirt surface. Two workers, one in a grey shirt and red helmet, and another in a blue shirt and yellow safety vest with a red helmet, are standing next to the front wheel. A yellow date stamp '2024/5/8' is in the bottom right corner.

444	GX-B1539/22-Y-24161	所检项目合格。	2024年6月18日	 A yellow wheel loader is parked on a dirt surface at a construction site. Two workers are standing next to it: one in a yellow safety vest and yellow helmet, and another in a white uniform and red helmet. The background shows some industrial buildings and hills under a blue sky. A yellow timestamp '2024/5/8' is visible in the bottom right corner of the photo.
445	GX-B1539/22-Y-24162	所检项目合格。	2024年6月18日	 A worker wearing a red helmet and a white uniform is seated inside the cab of a wheel loader, working on the controls. The background shows a construction site with hills. A yellow timestamp '2024/5/8' is visible in the bottom right corner of the photo.

446	GX-B1539/22-Y-24163	所检项目合格。	2024年6月18日	
447	GX-B1539/22-Y-24164	所检项目合格。	2024年6月18日	

448	GX-B1539/22-Y-24165	所检项目合格。	2024年6月18日	
449	GX-B1539/22-Y-24166	所检项目合格。	2024年6月18日	

450	GX-B1539/22-Y-24167	所检项目合格。	2024年6月18日	
451	GX-B1539/22-Y-24168	所检项目合格。	2024年6月18日	

452	GX-B1539/22-Y-24169	所检项目合格。	2024年6月18日	 A yellow wheel loader is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the vehicle. The date stamp '2024/5/10' is visible in the bottom right corner of the photo.
453	GX-B1539/22-Y-24170	所检项目合格。	2024年6月18日	 A yellow wheel loader is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the vehicle. The date stamp '2024/5/10' is visible in the bottom right corner of the photo.

454	GX-B1556/22-Y-24010	所检项目合格。	2024年6月18日	
455	GX-B1521/20-Y-24452	2024年6月18日	所检项目合格。	

456	GX-B1521/20-Y-24453	2024年6月18日	所检项目合格。	
457	GX-B1521/20-Y-24454	2024年6月18日	所检项目合格。	

458	GX-B1521/20-Y-24455	2024年6月18日	所检项目合格。	 A red LCMG ME136 excavator is shown in a desert environment. The excavator is positioned on sandy ground, and its arm is extended. A yellow date stamp '2024/5/28' is visible in the bottom right corner of the image.
459	GX-B1521/20-Y-24456	2024年6月18日	所检项目合格。	 A red LCMG ME136 excavator is shown in a desert environment, similar to the one in the first row. It is positioned on sandy ground, and its arm is extended. A yellow date stamp '2024/5/28' is visible in the bottom right corner of the image.

460	GX-B1521/20-Y-24457	2024年6月18日	所检项目合格。	
461	GX-B1521/20-Y-24448	2024年6月14日	所检项目合格。	

462	GX-B1521/20-Y-24294	2024年6月18日	所检项目合格。	 A red excavator is shown on a sandy beach, with its arm extended and bucket lowered. The background shows a clear sky and the ocean. A yellow timestamp '2024/4/4' is visible in the bottom right corner of the image.
463	GX-B1521/20-Y-24295	2024年6月18日	所检项目合格。	 A red excavator is shown on a rocky shore, with its arm extended and bucket lowered. Two workers in safety gear are standing nearby. The background shows a clear sky and the ocean. A yellow timestamp '2024/4/4' is visible in the bottom right corner of the image.

464	GX-B1521/20-Y-24296	2024年6月18日	所检项目合格。	
465	GX-B1521/20-Y-24297	2024年6月18日	所检项目合格。	

466	GX-B1521/20-Y-24298	2024年6月18日	所检项目合格。		
467	GX-B1521/20-Y-24299	2024年6月18日	所检项目合格。		

468	GX-B1521/20-Y-24301	2024年6月18日	所检项目合格。		
469	GX-B1521/20-Y-24302	2024年6月18日	所检项目合格。		

470	GX-B1539/22-Y-24231	2024年6月19日	所检项目合格。	 A yellow wheel loader with the license plate 'C-211' is parked on a dirt surface. Two workers wearing orange safety vests and hard hats stand in front of the vehicle. A yellow timestamp '2024/6/19' is visible in the bottom right corner of the photo.
471	GX-B1539/22-Y-24232	2024年6月19日	所检项目合格。	 A yellow wheel loader with the license plate 'C-212' is parked on a dirt surface. Two workers wearing orange safety vests and hard hats stand in front of the vehicle. A yellow timestamp '2024/6/19' is visible in the bottom right corner of the photo.

472	GX-B1385/21-Y-24039	2024年6月19日	所检项目合格。	
473	GX-B1385/21-Y-24040	2024年6月19日	所检项目合格。	

474	GX-B1385/21-Y-24041	2024年6月19日	所检项目合格。	
475	GX-B1385/21-Y-24042	2024年6月19日	所检项目合格。	

476	GX-B1385/21-Y-24043	2024年6月19日	所检项目合格。	
477	GX-B1385/21-Y-24044	2024年6月19日	所检项目合格。	

478	GX-B1385/21-Y-24045	2024年6月19日	所检项目合格。	
479	GX-B1385/21-Y-24046	2024年6月19日	所检项目合格。	

480	GX-B1385/21-Y-24047	2024年6月19日	所检项目合格。	
481	GX-B1385/21-Y-24048	2024年6月19日	所检项目合格。	

482	GX-B1385/21-Y-24049	2024年6月19日	所检项目合格。	 A worker wearing a black hard hat and safety glasses is standing next to a blue industrial machine. He is holding a white document or checklist and looking at it. On the machine, there is a yellow warning sign with a black triangle and the text '当心机械伤人' (Beware of mechanical injury). The date '2024/6/19' is visible in the bottom right corner of the photo.
483	GX-B1385/21-Y-24050	2024年6月19日	所检项目合格。	 A worker wearing a black hard hat and safety glasses is operating a blue industrial machine. He is holding a black cable or hose connected to the machine. The date '2024/6/19' is visible in the bottom right corner of the photo.

484	GX-B1385/21-Y-24051	2024年6月19日	所检项目合格。	
485	GX-B1385/21-Y-24052	2024年6月19日	所检项目合格。	

486	GX-B1385/21-Y-24053	2024年6月19日	所检项目合格。	
487	GX-B1404/20-Y-24013	2024年6月18日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

488	GX-B1404/20-Y-24014	2024年6月18日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
489	GX-B1495/20-Y-241221~241238	2024年6月18日	本次共检高压开关设备18台，18台高压开关设备所检项目合格。	

490	GX-B1495/20-Y-241239~ 241256	2024年6月18日	本次共检高压开关设备18台，18台高压开关设备所检项目合格。 。	
491	GX-B1495/20-Y-241257~ 241260	2024年6月18日	本次共检高压开关设备4台，4台高压开关设备所检项目合格。	

492	GX-B1495/20-Y-241261~ 241277	2024年6月18日	本次共检高压开关设备17台，17台高压开关设备所检项目合格。 。	
493	GX-B1495/20-Y-241278~ 241296	2024年6月18日	本次共检高压开关设备19台，19台高压开关设备所检项目合格。 。	

494	GX-B1495/20-Y-241297~ 241311	2024年6月18日	本次共检高压开关设备15台，15台高压开关设备所检项目合格。 。	
495	GX-B1495/20-Y-241312~ 241321	2024年6月18日	本次共检高压开关设备10台，10台高压开关设备所检项目合格。 。	

496	GX-B1495/20-Y-241322~ 241339	2024年6月18日	本次共检高压开关设备18台，18台高压开关设备所检项目合格。 。	
497	GX-B1495/20-Y-241340~ 241344	2024年6月18日	本次共检高压开关设备5台，5台高压开关设备所检项目合格。	

498	GX-B1416/22-Y-24073	2024年6月15日	综合判定：合格。	
499	GX-B1416/22-Y-24081	2024年6月15日	综合判定：合格。	

500	GX-B1416/22-Y-24082	2024年6月15日	综合判定：合格。	
501	GX-B1522/20-Y-24095	2024年6月19日	所检项目合格。	

502	GX-B1521/20-Y-24462	2023年6月20日	所检项目合格。	
503	GX-B1301/23-Y-24001	2024. 6. 20	综合判定:合格。	

504	GX-B1521/20-Y-24304	2024年6月20日	所检项目合格。	
505	GX-B1521/20-Y-24306	2024年6月20日	所检项目合格。	

506	GX-B1521/20-Y-24307	2024年6月20日	所检项目合格。	 A yellow excavator is shown in a construction or mining setting. Two workers wearing safety gear are standing near the machine. The date stamp '2024/4/28' is visible in the bottom right corner of the photo.
507	GX-B1521/20-Y-24308	2024年6月20日	所检项目合格。	 A yellow excavator is shown in a construction or mining setting. Two workers wearing safety gear are standing near the machine. The date stamp '2024/4/28' is visible in the bottom right corner of the photo.

508	GX-B1521/20-Y-24309	2024年6月20日	所检项目合格。	 A yellow excavator is shown at a construction site, with two workers in safety gear standing nearby. The date stamp '2024/4/28' is visible in the bottom right corner of the image.
509	GX-B1521/20-Y-24310	2024年6月20日	所检项目合格。	 A yellow excavator is shown at a construction site, with two workers in safety gear standing nearby. The date stamp '2024/4/28' is visible in the bottom right corner of the image.

510	GX-B1521/20-Y-24311	2024年6月20日	所检项目合格。	 A yellow excavator is shown in a desert-like environment, working on a dirt mound. A person in a red hard hat and safety vest stands near the base of the mound. The excavator's arm is extended, and it appears to be in the process of digging or moving earth. The date stamp in the bottom right corner of the image reads "2024/4/28".
511	GX-B1521/20-Y-24312	2024年6月20日	所检项目合格。	 A yellow excavator is shown in a desert-like environment, working on a dirt mound. Two people in red hard hats and safety vests stand near the base of the mound. The excavator's arm is extended, and it appears to be in the process of digging or moving earth. The date stamp in the bottom right corner of the image reads "2024/4/29".

512	GX-B1521/20-Y-24313	2024年6月20日	所检项目合格。	 A yellow Sdlg excavator is parked on a dirt field. Two workers wearing hard hats and safety vests are standing in front of the excavator. The date stamp '2024.4.29' is visible in the bottom right corner of the image.
513	GX-B1521/20-Y-24314	2024年6月20日	所检项目合格。	 A yellow excavator is shown working on a dirt mound. The excavator's arm is extended, and it appears to be digging or moving earth. The date stamp '2024.4.29' is visible in the bottom right corner of the image.

514	GX-B1521/20-Y-24316	2024年6月20日	所检项目合格。	 A red LCMG crawler crane is shown from a side profile on a sandy construction site. The crane's boom is extended upwards and to the right. A yellow date stamp '2024/6/20' is visible in the bottom right corner of the image.
515	GX-B1521/20-Y-24317	2024年6月20日	所检项目合格。	 A red LCMG crawler crane is shown from a different angle, possibly from the rear or side, on a sandy construction site. The crane's boom is extended upwards. A yellow date stamp '2024/6/20' is visible in the bottom right corner of the image.

516	GX-B1521/20-Y-24318	2024年6月20日	所检项目合格。	
517	GX-B1521/20-Y-24319	2024年6月20日	所检项目合格。	

518	GX-B1521/20-Y-24320	2024年6月20日	所检项目合格。	 A yellow excavator is shown with its bucket raised, positioned on a dark, rocky surface. A person in a white protective suit and helmet stands nearby. The background shows a large pile of dark material under a cloudy sky. A yellow timestamp '2024/4/30' is visible in the bottom right corner of the image.
519	GX-B1521/20-Y-24321	2024年6月20日	所检项目合格。	 A yellow excavator is shown with its bucket lowered, positioned on a dark, rocky surface. A person in a white protective suit and helmet stands nearby. The background shows a large pile of dark material under a cloudy sky. A yellow timestamp '2024/4/30' is visible in the bottom right corner of the image.

520	GX-B1521/20-Y-24322	2024年6月20日	所检项目合格。	 A yellow excavator is shown at a construction site. Two workers in safety gear are standing near the machine. The date stamp '2024/4/30' is visible in the bottom right corner of the photo.
521	GX-B1521/20-Y-24323	2024年6月20日	所检项目合格。	 A yellow excavator is shown at a construction site, positioned on a pile of dark material. Two workers in safety gear are standing near the machine. The date stamp '2024/4/30' is visible in the bottom right corner of the photo.

522	GX-B1521/20-Y-24324	2024年6月20日	所检项目合格。	
523	GX-B1521/20-Y-24325	2024年6月20日	所检项目合格。	

524	GX-B1521/20-Y-24326	2024年6月20日	所检项目合格。	 A yellow excavator with "LG" branding is shown at a construction site. Two workers in red safety gear are standing nearby. A yellow timestamp "2024/5/1" is visible in the bottom right corner of the photo.
525	GX-B1521/20-Y-24327	2024年6月20日	所检项目合格。	 A yellow excavator is shown with its bucket raised, displaying the number "HW1019" on the bucket's side. A worker in a yellow safety vest is standing next to the machine. A yellow timestamp "2024/5/1" is visible in the bottom right corner of the photo.

526	GX-B1521/20-Y-24328	2024年6月20日	所检项目合格。	 A yellow excavator is shown in a construction or mining site. Two workers in safety gear are standing in front of it. The excavator's arm is raised. A yellow timestamp '2024/5/1' is visible in the bottom right corner of the photo.
527	GX-B1521/20-Y-24329	2024年6月20日	所检项目合格。	 A yellow excavator is shown in a construction or mining site. Two workers in safety gear are standing in front of it. The excavator's arm is raised. A yellow timestamp '2024/5/1' is visible in the bottom right corner of the photo.

528	GX-B1521/20-Y-24330	2024年6月20日	所检项目合格。	 A yellow Sany excavator is shown in operation on a construction site. Two workers wearing hard hats and safety vests are standing in the foreground, observing the machine. The background shows a dirt mound under a bright sky. A yellow timestamp '2024/5/1' is visible in the bottom right corner of the image.
529	GX-B1521/20-Y-24331	2024年6月20日	所检项目合格。	 A yellow Sany excavator is shown with its bucket raised. Two workers in safety gear are standing next to it. The scene is a construction site with a dirt ground. A yellow timestamp '2024/5/1' is visible in the bottom right corner of the image.

530	GX-B1521/20-Y-24332	2024年6月20日	所检项目合格。	 A yellow excavator is shown at a construction site, with two workers in safety gear standing nearby. The excavator's arm is raised, and it appears to be working on a pile of material. A date stamp '2024/5/1' is visible in the bottom right corner of the image.
531	GX-B1521/20-Y-24333	2024年6月20日	所检项目合格。	 A yellow excavator is shown at a construction site, with two workers in safety gear standing nearby. The excavator's arm is raised, and it appears to be working on a pile of material. A date stamp '2024/5/1' is visible in the bottom right corner of the image.

532	GX-B1521/20-Y-24334	2024年6月20日	所检项目合格。	
533	GX-B1539/22-Y-24186	2024年6月20日	所检项目合格。	

534	GX-B1539/22-Y-24187	2024年6月20日	所检项目合格。	
535	GX-B1539/22-Y-24188	2024年6月20日	所检项目合格。	

536	GX-B1557/22-Y-24021	2024年6月21日	所检项目合格。	
537	GX-B1557/22-Y-24022	2024年6月21日	所检项目合格。	

538	GX-B1557/22-Y-24023	2024年6月21日	所检项目合格。	
539	GX-B1521/20-Y-24335	2024年6月21日	所检项目合格。	

540	GX-B1521/20-Y-24336	2024年6月21日	所检项目合格。	
541	GX-B1521/20-Y-24337	2024年6月21日	所检项目合格。	

542	GX-B1521/20-Y-24338	2024年6月21日	所检项目合格。	
543	GX-B1521/20-Y-24339	2024年6月21日	所检项目合格。	

544	GX-B1521/20-Y-24340	2024年6月21日	所检项目合格。	
545	GX-B1521/20-Y-24341	2024年6月21日	所检项目合格。	