

序号	报告编号	发布日期	结论	影像资料
546	GX-B1521/20-Y-24458	2024年6月21日	所检项目合格。	 A red tracked excavator with 'LCMB' branding on the boom, parked on a sandy surface. A yellow timestamp '2024/6/15' is visible in the bottom right corner of the photo.
547	GX-B1521/20-Y-24459	2024年6月21日	所检项目合格。	 A red tracked excavator with 'LCMB' branding on the boom, parked on a sandy surface. A yellow timestamp '2024/6/15' is visible in the bottom right corner of the photo.

548	GX-B1521/20-Y-24460	2024年6月21日	所检项目合格。	
549	GX-B1521/20-Y-24461	2024年6月21日	所检项目合格。	

550	GX-B1539/22-Y-24233	2024年6月21日	所检项目合格。	
551	GX-B1539/22-Y-24234	2024年6月21日	所检项目合格。	

552	GX-B1539/22-Y-24235	2024年6月21日	所检项目合格。	
553	GX-B1539/22-Y-24236	2024年6月21日	所检项目合格。	

554	GX-B1539/22-Y-24237	2024年6月21日	所检项目合格。	
555	GX-B1539/22-Y-24238	2024年6月21日	所检项目合格。	

556	GX-B1563/24-Y-24043	2024年6月21日	所检项目合格。	
557	GX-B1563/24-Y-24044	2024年6月21日	所检项目合格。	

558	GX-B1563/24-Y-24045	2024年6月21日	所检项目合格。	
559	GX-B1563/24-Y-24046	2024年6月21日	所检项目合格。	

560	GX-B1495/20-Y-241380~ 241397	2024. 6. 21	本次共检高压防爆开关18台，18台高压防爆开关所检项目合格。	
561	GX-B1495/20-Y-241398~ 241408	2024. 6. 21	本次共检高压防爆开关11台，11台高压防爆开关所检项目合格。	

562	GX-B1539/22-Y-24173	2024年6月21日	所检项目合格。	
563	GX-B1539/22-Y-24174	2024年6月21日	所检项目合格。	

564	GX-B1539/22-Y-24175	2024年6月21日	所检项目合格。	
565	GX-B1539/22-Y-24176	2024年6月21日	所检项目合格。	

566	GX-B1539/22-Y-24177	2024年6月21日	所检项目合格。	
567	GX-B1539/22-Y-24178	2024年6月21日	所检项目合格。	

568	GX-B1539/22-Y-24179	2024年6月21日	所检项目合格。	
569	GX-B1539/22-Y-24180	2024年6月21日	所检项目合格。	

570	GX-B1539/22-Y-24181	2024年6月21日	所检项目合格。	
571	GX-B1539/22-Y-24182	2024年6月21日	所检项目合格。	

572	GX-B1539/22-Y-24183	2024年6月21日	所检项目合格。	
573	GX-B1539/22-Y-24184	2024年6月21日	所检项目合格。	

574	GX-B1539/22-Y-24185	2024年6月21日	所检项目合格。	
575	GX-B1310/21-Y-24115	2024年6月21日	符合标准要求。	

576	GX-B1310/21-Y-24116	2024年6月21日	符合标准要求。	 A photograph of a male worker wearing a blue hard hat and a blue denim work shirt. He is holding a handheld electronic device with a yellow screen and is looking at it. The background shows industrial machinery. A yellow timestamp '2024/5/25' is visible in the bottom left corner of the photo.
577	GX-B1310/21-Y-24117	2024年6月21日	符合标准要求。	 A photograph of a male worker wearing a blue hard hat, safety glasses, and a blue denim work shirt. He is holding a handheld electronic device with a blue screen and is looking at it. The background shows industrial machinery. A yellow timestamp '2024/5/25' is visible in the bottom left corner of the photo.

578	GX-B1310/21-Y-24118	2024年6月21日	符合标准要求。	 A worker wearing a blue hard hat and work clothes is using a handheld electronic device to inspect a large, dark industrial machine. The device has a yellow screen. A vertical timestamp '2024/5/25' is visible in the bottom left corner of the photo.
579	GX-B1310/21-Y-24119	2024年6月21日	符合标准要求。	 A worker wearing a blue hard hat and work clothes is standing next to a large, blue metal cage structure. The worker is looking at something in their hands. A vertical timestamp '2024/5/25' is visible in the bottom left corner of the photo.

580	GX-B1310/21-Y-24120	2024年6月21日	符合标准要求。	
581	GX-B1310/21-Y-24121	2024年6月21日	符合标准要求。	

582	GX-B1310/21-Y-24122	2024年6月21日	符合标准要求。	 <p>A photograph showing a worker in a blue uniform and blue hard hat working on a large, dark industrial machine. The worker is positioned on a small platform or step, reaching towards the machine's components. The background shows a metallic wall with some pipes and a door. A yellow timestamp '2024/5/26' is visible in the bottom left corner of the image.</p>
583	GX-B1310/21-Y-24123	2024年6月21日	符合标准要求。	 <p>A photograph showing a worker in a blue uniform and blue hard hat working on a machine. The worker is wearing a safety harness and is positioned behind a metal safety cage. The worker is holding a tool or device, and there is a bright light source nearby. A yellow warning sign is visible on the machine. A yellow timestamp '2024/5/27' is visible in the bottom right corner of the image.</p>

584	GX-B1310/21-Y-24124	2024年6月21日	符合标准要求。	 <p>A photograph showing a worker in a blue uniform and blue helmet using a handheld device in a dark industrial setting. A warning sign is visible in the background. The date 2024/5/27 is printed in the bottom right corner of the image.</p>
585	GX-B1385/21-Y-24054	2024年6月21日	所检项目合格。	 <p>A photograph showing a worker in a grey uniform and red helmet standing in an industrial facility with machinery. The date 2024/4/2 is printed in the bottom right corner of the image.</p>

586	GX-B1385/21-Y-24055	2024年6月21日	所检项目合格。	 A worker wearing a red hard hat, a white protective suit, and a white face mask is inspecting a blue metal structure. The worker is holding a yellow bag. The date 2024/4/2 is visible in the bottom right corner of the photo.
587	GX-B1385/21-Y-24056	2024年6月21日	所检项目合格。	 A worker wearing a white protective suit and a white face mask is inspecting a blue metal structure. The worker is holding a blue tool. The date 2024/4/2 is visible in the bottom right corner of the photo.

588	GX-B1385/21-Y-24057	2024年6月21日	所检项目合格。	
589	GX-B1385/21-Y-24058	2024年6月21日	所检项目合格。	


590	GX-B1385/21-Y-24059	2024年6月21日	所检项目合格。	
591	GX-B1385/21-Y-24060	2024年6月21日	所检项目合格。	

592	GX-B1522/20-Y-24056	2024年6月22日	所检项目合格。	 A photograph of a yellow and grey drilling rig in a desert environment. Two workers in red safety gear are standing near the rig. The rig has a large vertical mast and various mechanical components. A yellow timestamp '2024/6/22' is visible in the bottom right corner of the image.
593	GX-B1522/20-Y-24057	2024年6月22日	所检项目合格。	 A photograph of a yellow and grey drilling rig in a desert environment. A worker in a grey uniform is standing near the rig. The rig has a large vertical mast and various mechanical components. A yellow timestamp '2024/6/22' is visible in the bottom right corner of the image.

594	GX-B1522/20-Y-24058	2024年6月22日	所检项目合格。	
595	GX-B1522/20-Y-24059	2024年6月22日	所检项目合格。	

596	GX-B1522/20-Y-24060	2024年6月22日	所检项目合格。	
597	GX-B1522/20-Y-24061	2024年6月22日	所检项目合格。	

598	GX-B1522/20-Y-24062	2024年6月22日	所检项目合格。	
599	GX-B1385/21-Y-24061	2024年6月21日	所检项目合格。	

600	GX-B1385/21-Y-24062	2024年6月21日	所检项目合格。	 <p>A photograph showing a worker in a red hard hat and white protective suit inspecting a blue metal fence at an industrial site. The worker is standing on a concrete platform. The background shows a brown building and a clear sky. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the image.</p>
601	GX-B1385/21-Y-24063	2024年6月21日	所检项目合格。	 <p>A photograph showing a worker in a red hard hat and brown protective suit standing on a metal walkway next to a blue corrugated metal structure. The worker is looking towards the camera. The background shows a hazy sky and some buildings. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the image.</p>

602	GX-B1385/21-Y-24064	2024年6月21日	所检项目合格。	
603	GX-B1385/21-Y-24065	2024年6月21日	所检项目合格。	

604	GX-B1385/21-Y-24066	2024年6月21日	所检项目合格。	 A worker wearing a white protective suit, a red hard hat, and a respirator mask is standing on a blue metal walkway. The worker is holding a green tool or hose connected to a red device. The background shows a large blue corrugated metal structure. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the photo.
605	GX-B1385/21-Y-24067	2024年6月21日	所检项目合格。	 A worker wearing a white protective suit, a red hard hat, and a respirator mask is pointing towards a blue corrugated metal structure. The worker is standing on a blue metal walkway. The background shows a large blue corrugated metal structure. A yellow timestamp '2024/4/3' is visible in the bottom right corner of the photo.

606	GX-B1385/21-Y-24068	2024年6月21日	所检项目合格。	
607	GX-B1385/21-Y-24074	2024年6月22日	所检项目合格。	

608	GX-B1385/21-Y-24075	2024年6月22日	所检项目合格。	 A worker in a blue uniform and hard hat is using a handheld device to inspect a large metal structure. The device has a white probe. A yellow timestamp '2024.5.25' is visible in the bottom left corner of the photo.
609	GX-B1385/21-Y-24076	2024年6月22日	所检项目合格。	 A worker in a blue uniform and hard hat is using a handheld device to inspect a large metal structure. The device has a white probe. A yellow timestamp '2024.5.25' is visible in the bottom left corner of the photo.

610	GX-B1385/21-Y-24077	2024年6月22日	所检项目合格。	 <p>A photograph showing a worker in a blue uniform and hard hat inspecting a metal structure in an industrial setting. The worker is standing on a platform, looking at a large metal component. The date 2024/5/25 is visible in the bottom left corner of the image.</p>
611	GX-B1385/21-Y-24078	2024年6月22日	所检项目合格。	 <p>A photograph showing two workers in blue uniforms and hard hats inspecting a metal structure in an industrial setting. One worker is holding a tool or document. The date 2024/5/25 is visible in the bottom left corner of the image.</p>

612	GX-B1385/21-Y-24079	2024年6月22日	所检项目合格。	
613	GX-B1385/21-Y-24080	2024年6月22日	所检项目合格。	

614	GX-B1321/20-Y-24430~ 24431	2024. 6. 24	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	 <p>2024/5/15</p>
615	GX-B1321/20-Y-24429	2024. 6. 24	所检项目合格。	 <p>2024/5/13</p>

616	GX-B1321/20-Y-24432~24438	2024. 6. 24	本次共检电力电缆 7条，7条电力电缆所 检项目合格。	
617	GX-B1321/20-Y-24439~24442	2024. 6. 24	本次共检电力电缆 4条，4条电力电缆所 检项目合格。	

618	GX-B1321/20-Y-24443~24444	2024. 6. 24	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	
619	GX-B1321/20-Y-24445~24448	2024. 6. 24	本次共检电力电缆 4条，4条电力电缆 所检项目合格。	

620	GX-B1310/21-Y-24125	2024. 6. 20	符合标准要求。	
621	GX-B1310/21-Y-24126	2024. 6. 20	符合标准要求。	

622	GX-B1427/21-Y-24125	2024. 6. 20	无缺陷磁痕显示。	
623	GX-B1427/21-Y-24126	2024. 6. 20	无缺陷磁痕显示。	

624	GX-B1563/24-Y-24029	2024年6月25日	所检项目合格。	
625	GX-B1563/24-Y-24030	2024年6月25日	所检项目合格。	

626	GX-B1563/24-Y-24031	2024年6月25日	所检项目合格。	
627	GX-B1559/22-Y-24020	2024年6月25日	所检项目合格。	

628	GX-B1415/22-Y-24010	2024. 6. 25	综合判定：合格。	
629	GX-B1424/20-Y-24008	2024年6月26日	依据NB/T 10176-2019单轨吊车综合判定合格； 依据MT/T 220-1990 尾气所检项目合格。	

630	GX-B1424/20-Y-24009	2024年6月26日	依据NB/T 10176-2019单轨吊车综合判定合格； 依据MT/T 220-1990 尾气所检项目合格。	 <p>2024/5/26</p>
631	GX-B1424/20-Y-24010	2024年6月26日	依据NB/T 10176-2019单轨吊车综合判定合格； 依据MT/T 220-1990 尾气所检项目合格。	 <p>2024/5/26</p>

632	GX-B1424/20-Y-24007	2024年6月25日	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。	
633	GX-B1495/20-Y-241352~241358	2024年6月26日	本次共检高压交流断路器7台，7台高压交流断路器所检项目合格。	

634	GX-B1495/20-Y-241345~241351	2024年6月26日	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	
635	GX-B1547/20-Y-24250~24256	2024年6月26日	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	

636	GX-B1336/22-Y-24030~24031	2024年6月26日	本次共检母线2条，2条母线所检项目合格。	
637	GX-B1495/20-Y-241359~241379	2024年6月26日	本次共检电流互感器21只，21只电流互感器所检项目合格。	

638	GX-B1404/20-Y-24015	2024年6月26日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
639	GX-B1404/20-Y-24016	2024年6月26日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

640	GX-B1556/22-Y-24018	2024年6月25日	所检项目合格。	
641	GX-B1415/22-Y-24011	2024年6月26日	综合判定：合格。	