


序号	报告编号	发布日期	结论	影像资料
58	GX-B1451/20-6-24624~24630	2024/7/15	本次共检高压开关柜7台，7台高压开关柜所检项目合格。 。	
59	GX-B1310/21-6-24202	2024/7/15	符合标准要求	


60	GX-B1310/21-6-24203	2024/7/15	符合标准要求		 2024 06 09	
61	GX-B1427/21-6-24063	2024/7/15	无缺陷磁痕显示		 2024 06 09	
62	GX-B1427/21-6-24064	2024/7/15	无缺陷磁痕显示		 2024 06 09	

63	GX-B1495/20-6-24829~24843	2024/7/13	本次共检高压防爆开关15台，15台高压防爆开关所检项目合格。	 2024 05 22
64	GX-B1495/20-6-24844~24853	2024/7/13	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	 2024 05 23
65	GX-B1495/20-6-24854~24866	2024/7/13	本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。	 2024 05 24

66	GX-B1495/20-6-24867~24881	2024/7/13	本次共检高压防爆开关15台，15台高压防爆开关所检项目合格。	 2024 05 25
67	GX-B1495/20-6-24882~24898	2024/7/13	本次共检高压防爆开关17台，17台高压防爆开关所检项目合格。	 2024 05 27
68	GX-B1495/20-6-24899~24913	2024/7/13	本次共检高压防爆开关15台，15台高压防爆开关所检项目合格。	 2024 05 28

69	GX-B1495/20-6-24914~24922	2024/7/13	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。	
70	GX-B1495/20-6-24923~24936	2024/7/13	本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。	
71	GX-B1495/20-6-24937~24949	2024/7/13	本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。	

72	GX-B1495/20-6-24950~24960	2024/7/13	本次共检高压防爆开关11台，11台高压防爆开关所检项目合格。	 2024 06 01
73	GX-B1495/20-6-24961~24977	2024/7/13	本次共检高压防爆开关17台，17台高压防爆开关所检项目合格。	 2024 06 02
74	GX-B1495/20-6-24978~24991	2024/7/13	本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。	 2024 06 03


75	GX-B1495/20-6-24992~241007	2024/7/13	本次共检高压防爆开关16台，16台高压防爆开关所检项目合格。	
76	GX-B1495/20-6-241008~241023	2024/7/13	本次共检高压防爆开关16台，16台高压防爆开关所检项目合格。	
77	GX-B1495/20-6-241024~241036	2024/7/13	本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。	

78	GX-B1495/20-6-241037~241044	2024/7/13	本次共检高压防爆开关8台，8台高压防爆开关所检项目合格。	
79	GX-B1495/20-6-241045~241054	2024/7/13	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	
80	GX-B1416/22-6-24004	2024/7/15	综合判定：合格。	

81	GX-B1416/22-6-24005	2024/7/15	综合判定：合格。		
82	GX-B1328/20-6-24086	2024/7/12	所检项目合格		
83	GX-B1328/20-6-24087	2024/7/12	所检项目合格		

84	GX-B1499/23-6-24023	2024/7/15	所检项目合格	
85	GX-B1499/23-6-24024	2024/7/15	所检项目合格	
86	GX-B1499/23-6-24025	2024/7/15	所检项目合格	


87	GX-B1322/21-6-24250~24255	2024/7/16	所检项目合格		
88	GX-B1303/21-6-24018	2024/7/5	综合判定：合格		
89	GX-B1303/21-6-24019	2024/7/5	综合判定：合格		

90	GX-B1303/21-6-24020	2024/7/5	综合判定：合格	
91	GX-B1303/21-6-24021	2024/7/5	综合判定：合格	
92	GX-B1328/20-6-24082	2024/7/18	所检项目合格	

93	GX-B1321/20-6-24445~24454	2024/7/16	所检项目合格	
94	GX-B1321/20-6-24455~24465	2024/7/16	所检项目合格	
95	GX-B1321/20-6-24466~24475	2024/7/16	所检项目合格	

96	GX-B1321/20-6-24476~24485	2024/7/16	所检项目合格	
97	GX-B1321/20-6-24486~24495	2024/7/16	所检项目合格	
98	GX-B1321/20-6-24496~24498	2024/7/16	所检项目合格	

99	GX-B1321/20-6-24499~24509	2024/7/16	所检项目合格	
100	GX-B1321/20-6-24510~24519	2024/7/16	所检项目合格	
101	GX-B1321/20-6-24520~24527	2024/7/16	所检项目合格	

102	GX-B1321/20-6-24528~24536	2024/7/16	所检项目合格	
103	GX-B1321/20-6-24537~24545	2024/7/16	所检项目合格	
104	GX-B1321/20-6-24546~24555	2024/7/16	所检项目合格	

105	GX-B1321/20-6-24556~24565	2024/7/16	所检项目合格	 2024 06 02
106	GX-B1321/20-6-24566~24575	2024/7/16	所检项目合格	 2024 06 03
107	GX-B1321/20-6-24576~24586	2024/7/16	所检项目合格	 2024 06 04

108	GX-B1321/20-6-24587~24598	2024/7/16	所检项目合格	 2024 06 05
109	GX-B1321/20-6-24599~24610	2024/7/16	所检项目合格	 2024 06 06
110	GX-B1321/20-6-24618~24627	2024/7/16	所检项目合格	 2024 06 08

111	GX-B1321/20-6-24611~24617	2024/7/16	所检项目合格	
112	GX-B1321/20-6-24628~24639	2024/7/16	所检项目合格	
113	GX-B1304/21-6-24027	2024/7/16	综合判定合格	

114	GX-B1304/21-6-24028	2024/7/16	综合判定合格	
115	GX-B1304/21-6-24029	2024/7/16	综合判定合格	
116	GX-B1304/21-6-24026	2024/7/17	综合判定合格	

117	GX-B1427/21-6-24050	2024/7/17	符合标准要求		
118	GX-B1428/21-6-24010	2024/7/17	无缺陷迹痕显示		
119	GX-B1428/21-6-24011	2024/7/17	无缺陷迹痕显示		

120	GX-B1428/21-6-24012	2024/7/17	无缺陷迹痕显示		 2024 05 22	
121	GX-B1428/21-6-24013	2024/7/17	无缺陷迹痕显示		 2024 05 22	
122	GX-B1428/21-6-24014	2024/7/17	无缺陷迹痕显示		 2024 05 22	

123	GX-B1428/21-6-24015	2024/7/17	无缺陷迹痕显示			
124	GX-B1428/21-6-24016	2024/7/17	无缺陷迹痕显示			
125	GX-B1428/21-6-24017	2024/7/17	无缺陷迹痕显示			

126	GX-B1428/21-6-24018	2024/7/17	无缺陷迹痕显示			
127	GX-B1428/21-6-24019	2024/7/17	无缺陷迹痕显示			
128	GX-B1428/21-6-24020	2024/7/17	无缺陷迹痕显示			

129	GX-B1495/20-6-241065~241080	2024/7/17	所检项目合格	 2024 05 05
130	GX-B1495/20-6-241055~241064	2024/7/17	所检项目合格	  2024 5 20
131	GX-B1495/20-6-24633~24641	2024/7/17	所检项目合格	  2024 06 04

132	GX-B1495/20-6-24642~24646	2024/7/17	所检项目合格	
133	GX-B1495/20-6-24647~24660	2024/7/17	所检项目合格	
134	GX-B1495/20-6-24661~24677	2024/7/17	所检项目合格	

135	GX-B1495/20-6-24678	2024/7/17	所检项目合格		
136	GX-B1427/21-6-24056	2024/7/18	符合标准要求		
137	GX-B1427/21-6-24057	2024/7/18	符合标准要求		

138	GX-B1427/21-6-24058	2024/7/18	符合标准要求		
139	GX-B1427/21-6-24059	2024/7/18	符合标准要求		
140	GX-B1427/21-6-24060	2024/7/18	符合标准要求		

141	GX-B1427/21-6-24061	2024/7/18	符合标准要求			
142	GX-B1310/21-6-24181	2024/7/18	符合标准要求			
143	GX-B1310/21-6-24182	2024/7/18	符合标准要求			

144	GX-B1310/21-6-24183	2024/7/18	符合标准要求			
145	GX-B1310/21-6-24184	2024/7/18	符合标准要求			
146	GX-B1310/21-6-24185	2024/7/18	符合标准要求			

147	GX-B1310/21-6-24186	2024/7/18	符合标准要求			
148	GX-B1309/21-6-24035	2024/7/18	所检项目合格			
149	GX-B1500/21-6-24134	2024/7/18	综合判定合格			

150	GX-B1500/21-6-24135	2024/7/18	综合判定合格		
151	GX-B1500/21-6-24136	2024/7/18	综合判定合格		
152	GX-B1500/21-6-24137	2024/7/18	综合判定合格		

153	GX-B1309/21-6-24036	2024/7/18	所检项目合格		 2024 06 29	
154	GX-B1500/21-6-24138	2024/7/18	综合判定合格		 2024 06 29	
155	GX-B1500/21-6-24139	2024/7/18	综合判定合格		 2024 06 29	

156	GX-B1500/21-6-24140	2024/7/18	综合判定合格		 A photograph showing a worker in a red hard hat and safety vest operating a green industrial machine. The worker is holding a blue cloth or tool. The background is an industrial interior with a corrugated metal wall. A timestamp '2024 06 29' is visible in the bottom right corner of the image.	
-----	---------------------	-----------	--------	--	---	--