



序号	报告编号	发布日期	结论	影像资料
133	GX-B1328/20-5-24117	2024. 7. 19	本次共检绝缘手套6只，6只绝缘手套合格。	
134	GX-B1328/20-5-24118	2024. 7. 19	本次共检绝缘鞋6只，6只绝缘鞋合格。	
135	GX-B1328/20-5-24111	2024. 7. 19	本次共检绝缘手套46只，46只绝缘手套合格。	



136	GX-B1328/20-5-24112	2024. 7. 19	本次共检绝缘鞋42只，42只绝缘鞋合格。	
137	GX-B1310/21-5-24182	2024. 7. 18	符合标准要求。	
138	GX-B1310/21-5-24179	2024. 7. 18	符合标准要求。	


139	GX-B1428/21-5-24012	2024. 7. 18	无缺陷迹痕显示。	
140	GX-B1428/21-5-24013	2024. 7. 18	无缺陷迹痕显示。	
141	GX-B1310/21-5-24180	2024. 7. 18	符合标准要求。	

142	GX-B1310/21-5-24181	2024. 7. 18	符合标准要求。	
143	GX-B1321/20-5-24803-24807	2024. 7. 19	所检项目合格	
144	GX-B1321/20-5-24808-24816	2024. 7. 19	所检项目合格	

145	GX-B1310/21-5-24190	2024. 7. 19	符合标准要求。	
146	GX-B1310/21-5-24191	2024. 7. 19	符合标准要求。	
147	GX-B1310/21-5-24192	2024. 7. 19	符合标准要求。	


148	GX-B1310/21-5-24193	2024. 7. 19	符合标准要求。	
149	GX-B1310/21-5-24194	2024. 7. 19	符合标准要求。	
150	GX-B1310/21-5-24195	2024. 7. 19	符合标准要求。	

151	GX-B1310/21-5-24196	2024. 7. 19	符合标准要求。	
152	GX-B1310/21-5-24197	2024. 7. 19	符合标准要求。	
153	GX-B1310/21-5-24198	2024. 7. 19	符合标准要求。	

154	GX-B1310/21-5-24199	2024. 7. 19	符合标准要求。	
155	GX-B1310/21-5-24200	2024. 7. 19	符合标准要求。	
156	GX-B1310/21-5-24201	2024. 7. 19	符合标准要求。	

157	GX-B1310/21-5-24202	2024. 7. 19	符合标准要求。	
158	GX-B1321/20-5-24938	2024/7/22	所检项目合格。	
159	GX-B1321/20-5-24912~24914	2024. 7. 19	所检项目合格	

160	GX-B1300/23-5-24023	2024/7/22	综合判定：合格。	
161	GX-B1300/23-5-24024	2024/7/22	综合判定：合格。	
162	GX-B1300/23-5-24028	2024/7/22	综合判定：合格。	

163	GX-B1300/23-5-24026	2024. 7. 22	综合判定：合格。	 A vertical measuring scale with a green frame and a white scale, used for measuring the height of a machine or structure. The scale is marked in meters and centimeters. The date 2024.06.06 is visible in the bottom right corner of the image.
164	GX-B1306/23-5-24033	2024/7/23	综合判定：合格。	 A worker wearing a red hard hat and a blue uniform is standing next to a yellow machine. The machine has a blue logo and the text '5#'. The worker is holding a red toolbox. The date 2024/04/18 is visible in the bottom right corner of the image.

165	GX-B1424/20-5-24062	2024/7/23	依据NB/T 10176-2019单轨吊车 所检项目合格；依据MT/T 220- 1990 尾气所检项目合格。	
166	GX-B1310/21-5-24178	2024/7/23	符合标准要求。	

167	GX-B1300/23-5-24025	2024. 7. 19	综合判定：合格。	
168	GX-B1300/23-5-24027	2024. 7. 25	综合判定：合格。	
169	GX-B1559/22-5-24010	2024. 7. 25	所检项目合格。	

170	GX-B1321/20-5-24939~24950	2024. 7. 25	本次共检电力电缆12条，12条电力电缆所检项目合格。	 A worker in a blue uniform and red helmet is working on a cable in a rack. The date 2024.3.3 is visible in the bottom right corner of the image.
171	GX-B1321/20-5-24964~24967	2024. 7. 25	本次共检电力电缆4条，4条电力电缆所检项目合格。	 A worker in a dark jacket and helmet is working on a cable in a rack. The date 2024.3.5 is visible in the bottom right corner of the image.
172	GX-B1321/20-5-24951~24963	2024. 7. 25	本次共检电力电缆13条，13条电力电缆所检项目合格。	 A worker in a dark uniform and helmet is working on a cable in a rack. The date 2024.3.4 is visible in the bottom right corner of the image.