


序号	报告编号	发布日期	结论	影像资料
18	GX-B1559/22-P-24091	2024. 9. 6	所检项目合格。	 A worker wearing a white long-sleeved shirt with a logo and a red hard hat is kneeling on the ground next to a yellow excavator. He is looking at a piece of equipment, possibly a sensor or a diagnostic tool, attached to the machine. The background shows an outdoor setting with some greenery and a building.
19	GX-B1559/22-P-24092	2024. 9. 6	所检项目合格。	 A worker wearing a white long-sleeved shirt with a logo and a red hard hat is kneeling on the ground next to a yellow excavator. He is holding a long, thin metal rod or probe, which he is using to inspect a part of the machine. The background shows an outdoor setting with some greenery and a building.

20	GX-B1559/22-P-24093	2024. 9. 6	所检项目合格。	 <p>2024.8.29</p>
21	GX-B1559/22-P-24094	2024. 9. 6	所检项目合格。	 <p>2024.8.30</p>
22	GX-B1559/22-P-24095	2024. 9. 6	所检项目合格。	 <p>2024.8.30</p>

23	GX-B1559/22-P-24096	2024. 9. 9	所检项目合格	 <p>2024.8.24</p>
24	GX-B1303/21-P-24002	2024. 9. 9	综合判定：合格。	 <p>2024/7/26</p>