

序号	报告编号	发布日期	结论	影像资料
24	GX-B1361/22-A-241127	2024/11/4	所检项目合格	
25	GX-B1361/22-A-241128	2024/11/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1362/23-A-24407	2024/11/4	所检项目合格	
27	GX-B1362/23-A-24408	2024/11/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1362/23-A-24409	2024/11/4	所检项目合格	
29	GX-B1362/23-A-24410	2024/11/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
30	GX-B1362/23-A-24411	2024/11/4	所检项目合格		
31	GX-B1362/23-A-24412	2024/11/4	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
32	GX-B1362/23-A-24413	2024/11/4	所检项目合格	
33	GX-B1362/23-A-24414	2024/11/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1362/23-A-24415	2024/11/4	所检项目合格	
35	GX-B1362/23-A-24416	2024/11/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1362/23-A-24417	2024/11/4	所检项目合格	
37	GX-B1362/23-A-24418	2024/11/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料	
38	GX-B1362/23-A-24419	2024/11/4	所检项目合格		
39	GX-B1362/23-A-24420	2024/11/4	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
40	GX-B1362/23-A-24421	2024/11/4	所检项目合格	
41	GX-B1362/23-A-24422	2024/11/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1362/23-A-24423	2024/11/4	所检项目合格	
43	GX-B1362/23-A-24424	2024/11/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1362/23-A-24425	2024/11/4	所检项目合格	
45	GX-B1361/22-A-241124	2024/11/5	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1361/22-A-241125	2024/11/5	所检项目合格	
47	GX-B1361/22-A-241126	2024/11/5	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
48	GX-B1361/22-A-241129	2024/11/5	所检项目合格	
49	GX-B1361/22-A-241130	2024/11/5	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
50	GX-B1361/22-A-241131	2024/11/5	所检项目合格	
51	GX-B1361/22-A-241132	2024/11/5	不合格	

序号	报告编号	发布日期	结论	影像资料	
52	GX-B1361/22-A-241133	2024/11/6	所检项目合格		
53	GX-B1361/22-A-241134	2024/11/6	所检项目合格		

序号	报告编号	发布日期	结论	影像资料
54	GX-B1362/23-A-24426	2024/11/5	所检项目合格	 A photograph showing two male workers in grey work uniforms operating a large industrial machine in a workshop. One worker is on the left, and the other is on the right, both focused on their task. A yellow timestamp '2024/10/26' is visible in the bottom right corner of the image.
55	GX-B1362/23-A-24427	2024/11/5	所检项目合格	 A photograph showing a worker in a grey work uniform operating a machine in a workshop. The worker is in the foreground, focused on his work. A yellow timestamp '2024/10/26' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
56	GX-B1362/23-A-24428	2024/11/5	所检项目合格	
57	GX-B1362/23-A-24429	2024/11/6	合格	

序号	报告编号	发布日期	结论	影像资料
58	GX-B1362/23-A-24430	2024/11/5	不合格	
59	GX-B1362/23-A-24431	2024/11/5	不合格	

序号	报告编号	发布日期	结论	影像资料
60	GX-B1362/23-A-24432	2024/11/5	合格	
61	GX-B1362/23-A-24433	2024/11/6	不合格	

序号	报告编号	发布日期	结论	影像资料
62	GX-B1362/23-A-24434	2024/11/5	不合格	
63	GX-B1362/23-A-24435	2024/11/5	合格	

序号	报告编号	发布日期	结论	影像资料
64	GX-B1362/23-A-24436	2024/11/5	合格	
65	GX-B1362/23-A-24437	2024/11/5	合格	

序号	报告编号	发布日期	结论	影像资料
66	GX-B1362/23-A-24438	2024/11/5	合格	
67	GX-B1362/23-A-24439	2024/11/5	合格	

序号	报告编号	发布日期	结论	影像资料
68	GX-B1362/23-A-24440	2024/11/5	合格	 A photograph showing two male workers in grey work jackets and gloves operating a large industrial machine in a workshop. The worker on the left is adjusting a component on the machine, while the worker on the right is observing. A yellow timestamp '2024/10/29' is visible in the bottom right corner of the image.
69	GX-B1362/23-A-24441	2024/11/5	合格	 A photograph showing two male workers in grey work jackets and gloves operating a large industrial machine in a workshop. The worker on the left is adjusting a component on the machine, while the worker on the right is observing. A yellow timestamp '2024/10/29' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
70	GX-B1362/23-A-24442	2024/11/5	合格	
71	GX-B1362/23-A-24443	2024/11/5	合格	

序号	报告编号	发布日期	结论	影像资料
72	GX-B1362/23-A-24444	2024/11/5	合格	 A photograph showing two male workers in grey work jackets operating a large industrial machine in a workshop. The worker on the right is leaning over the machine, while the one on the left is standing nearby. A yellow timestamp '2024/10/30' is visible in the bottom right corner of the image.
73	GX-B1362/23-A-24445	2024/11/5	合格	 A photograph showing two male workers in grey work jackets operating a large industrial machine in a workshop. The worker on the right is leaning over the machine, while the one on the left is standing nearby. A yellow timestamp '2024/10/31' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
74	GX-B1362/23-A-24446	2024/11/5	合格	 A photograph showing two male workers in grey work uniforms and white gloves operating a large industrial machine. They are positioned on either side of a long, narrow tray filled with numerous small, light-colored components. The machine has a control panel with a dial and a handle. The background shows a workshop environment with various tools and equipment. A yellow timestamp '2024/11/1' is visible in the bottom right corner of the image.
75	GX-B1362/23-A-24447	2024/11/5	合格	 A photograph showing two male workers in grey work uniforms and white gloves operating a large industrial machine. They are positioned on either side of a long, narrow tray filled with numerous small, light-colored components. The machine has a control panel with a dial and a handle. The background shows a workshop environment with various tools and equipment. A yellow timestamp '2024/11/1' is visible in the bottom right corner of the image.