

序号	报告编号	发布日期	结论	影像资料	
127	GX-B1362/23-A-25001	2025/1/8	所检项目合格		
128	GX-B1362/23-A-25002	2025/1/8	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
129	GX-B1362/23-A-25003	2025/1/8	所检项目合格		
130	GX-B1361/22-A-25016	2025/1/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
131	GX-B1361/22-A-25017	2025/1/9	所检项目合格		
132	GX-B1361/22-A-25018	2025/1/9	不合格		

序号	报告编号	发布日期	结论	影像资料	
133	GX-B1361/22-A-25019	2025/1/9	所检项目合格		 A photograph showing two male workers in a workshop. The worker on the left is operating a large industrial machine, possibly a lathe or mill. The worker on the right is standing next to him, looking down at a workbench. There are various tools and materials visible in the background. A yellow timestamp '2025/1/5' is visible in the bottom right corner of the image.
134	GX-B1361/22-A-25020	2025/1/9	所检项目合格		 A photograph showing two male workers in a workshop. The worker on the left is operating a large industrial machine, possibly a lathe or mill. The worker on the right is standing next to him, looking down at a workbench. There are various tools and materials visible in the background. A yellow timestamp '2025/1/5' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料	
135	GX-B1361/22-A-25021	2025/1/9	所检项目合格		
136	GX-B1361/22-A-25022	2025/1/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
137	GX-B1361/22-A-25023	2025/1/9	所检项目合格		
138	GX-B1361/22-A-25024	2025/1/9	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
139	GX-B1361/22-A-25025	2025/1/9	所检项目合格		
140	GX-B1362/23-A-25004	2025/1/13	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
141	GX-B1362/23-A-25005	2025/1/13	所检项目合格		
142	GX-B1362/23-A-25006	2025/1/13	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
143	GX-B1362/23-A-25007	2025/1/13	所检项目合格		
144	GX-B1362/23-A-25024	2025/1/15	不合格		

序号	报告编号	发布日期	结论	影像资料	
145	GX-B1362/23-A-25026	2025/1/15	所检项目合格		
146	GX-B1361/22-A-25035	2025/1/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
147	GX-B1361/22-A-25036	2025/1/15	所检项目合格		
148	GX-B1361/22-A-25037	2025/1/15	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
149	GX-B1361/22-A-25038	2025/1/15	所检项目合格		 A photograph showing a male worker in a light-colored work jacket and gloves, focused on operating a machine in a workshop. The machine has a yellow frame. In the background, another worker is visible. A yellow timestamp '2025/1/11' is in the bottom right corner.
150	GX-B1362/23-A-25008	2025/1/14	合格		 A photograph showing two male workers in light-colored work jackets and gloves, working together at a machine in a workshop. The machine has a yellow frame. A yellow timestamp '2025/1/6' is in the bottom right corner.

序号	报告编号	发布日期	结论	影像资料	
151	GX-B1362/23-A-25009	2025/1/14	合格		
152	GX-B1362/23-A-25010	2025/1/14	合格		

序号	报告编号	发布日期	结论	影像资料	
153	GX-B1362/23-A-25011	2025/1/14	合格		
154	GX-B1362/23-A-25012	2025/1/14	合格		

序号	报告编号	发布日期	结论	影像资料	
155	GX-B1362/23-A-25013	2025/1/14	合格		
156	GX-B1362/23-A-25014	2025/1/15	合格		

序号	报告编号	发布日期	结论	影像资料	
157	GX-B1362/23-A-25015	2025/1/15	合格		
158	GX-B1362/23-A-25016	2025/1/15	合格		

序号	报告编号	发布日期	结论	影像资料	
159	GX-B1362/23-A-25017	2025/1/15	合格		 A photograph showing two male workers in grey work uniforms operating a large industrial machine in a workshop. The worker on the right is leaning over the machine, while the one on the left is standing slightly behind. A yellow timestamp '2025/1/8' is visible in the bottom right corner of the image.
160	GX-B1362/23-A-25018	2025/1/15	合格		 A photograph showing two male workers in grey work uniforms in a workshop. One worker is operating a large industrial machine, and the other is standing next to it, looking down at something. A yellow timestamp '2025/1/8' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料	
161	GX-B1362/23-A-25019	2025/1/15	合格		
162	GX-B1362/23-A-25020	2025/1/15	合格		

序号	报告编号	发布日期	结论	影像资料	
163	GX-B1362/23-A-25021	2025/1/15	合格		
164	GX-B1362/23-A-25022	2025/1/15	合格		

序号	报告编号	发布日期	结论	影像资料	
165	GX-B1362/23-A-25023	2025/1/15	合格		
166	GX-B1362/23-A-25030	2025/1/16	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
167	GX-B1362/23-A-25031	2025/1/16	所检项目合格		
168	GX-B1362/23-A-25032	2025/1/16	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
169	GX-B1362/23-A-25033	2025/1/16	所检项目合格		