

序号	报告编号	发布日期	结论	影像资料	
144	GX-B1305/21-6-24015	2024/5/20	所检项目合格。		
145	GX-B1520/20-6-24053	2024/5/21	综合判定：合格。		

146	GX-B1520/20-6-24054	2024/5/21	综合判定：合格。	
147	GX-B1520/20-6-24055	2024/5/21	综合判定：合格。	
148	GX-B1520/20-6-24049	2024/5/21	综合判定：合格。	

149	GX-B1520/20-6-24056	2024/5/21	综合判定：合格。	 A worker in a grey uniform and red hard hat stands next to a large white pipe. A red toolbox is on the ground. A white bucket is visible. The background shows a dirt area and a white car. The date 2024 05 01 is printed in the bottom right corner.
150	GX-B1520/20-6-24057	2024/5/21	综合判定：合格。	 A worker in a grey uniform and red hard hat stands next to a large white pipe. A red toolbox is on the ground. A white bucket is visible. The background shows a dirt area and a white car. The date 2024 05 01 is printed in the bottom right corner.
151	GX-B1520/20-6-24058	2024/5/21	综合判定：合格。	 A worker in a grey uniform and red hard hat stands next to a large white pipe. A red toolbox is on the ground. A white bucket is visible. The background shows a dirt area and a white car. The date 2024 05 01 is printed in the bottom right corner.

152	GX-B1307/20-6-24031	2024/5/21	综合判定：合格。	
153	GX-B1307/20-6-24032	2024/5/21	综合判定：合格。	
154	GX-B1307/20-6-24033	2024/5/21	综合判定：合格。	

155	GX-B1307/20-6-24034	2024/5/21	综合判定：合格。	
156	GX-B1307/20-6-24035	2024/5/21	综合判定：合格。	
157	GX-B1307/20-6-24039	2024/5/21	综合判定：合格。	

158	GX-B1307/20-6-240409	2024/5/21	综合判定：合格。	
159	GX-B1307/20-6-24036	2024/4/24	综合判定：合格。	
160	GX-B1307/20-6-24037	2024/4/24	综合判定：合格。	

161	GX-B1307/20-6-24038	2024/4/24	综合判定：合格。	
162	GX-B1499/23-6-24005	2024/5/22	所检项目合格。	
163	GX-B1499/23-6-24006	2024/5/22	所检项目合格。	

164	GX-B1499/23-6-24007	2024/5/22	所检项目合格。	
-----	---------------------	-----------	---------	---