

序号	报告编号	发布日期	结论	影像资料
319	GX-B1508/22-A-25009	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
320	GX-B1508/22-A-25010	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
321	GX-B1508/22-A-25011	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
322	GX-B1363/22-A-25357	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
323	GX-B1363/22-A-25361	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
324	GX-B1363/22-A-25366	2025/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
325	GX-B1363/22-A-25362	2025/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
326	GX-B1363/22-A-25363	2025/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
327	GX-B1363/22-A-25359	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
328	GX-B1508/22-A-25011	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
329	GX-B1363/22-A-25377	2025/6/26	所检项目合格。	 <p>The photograph shows two men in light blue work shirts and dark trousers inspecting a large, rusted industrial boiler. One man is leaning into the open door of the boiler, while the other stands beside him, looking on. The boiler is situated in a room with white walls and a window with a black frame. A green floor fan is visible to the right of the boiler. The date '2025.06.25' is printed in orange in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
330	GX-B1364/22-A-25667	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
331	GX-B1364/22-A-25668	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
332	GX-B1364/22-A-25669	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
333	GX-B1364/22-A-25670	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
334	GX-B1364/22-A-25682	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
335	GX-B1364/22-A-25683	2025/6/24	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
336	GX-B1364/22-A-25684	2025/6/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
337	GX-B1364/22-A-25685	2025/6/24	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
338	GX-B1364/22-A-25686	2025/6/24	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
339	GX-B1364/22-A-25704	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
340	GX-B1364/22-A-25698	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
341	GX-B1364/22-A-25702	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
342	GX-B1364/22-A-25703	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
343	GX-B1364/22-A-25699	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
344	GX-B1364/22-A-25700	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
345	GX-B1364/22-A-25701	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
346	GX-B1364/22-A-25714	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
347	GX-B1364/22-A-25712	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
348	GX-B1364/22-A-25713	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
349	GX-B1364/22-A-25710	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
350	GX-B1364/22-A-25711	2025/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
351	GX-B1363/22-A-25367	2025/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
352	GX-B1363/22-A-25378	2025/6/27	所检项目合格。	 <p>The photograph shows two men in light blue short-sleeved shirts and dark trousers inspecting a large, rusted industrial furnace. One man is on the left, looking into the furnace's open door, while the other is on the right, wearing gloves and working on the interior. The furnace has a yellow warning triangle on its front. In the background, there is a window with a view of trees and a green floor fan. A date stamp '2025.06.26' is visible in the bottom right corner of the photo.</p>